


Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT NON-PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey				11/27/22	
					Field Operations	
					Page 1 of 1	Rev. No. 0
					Submitted By:	
				30 Minute Avg H ₂ S Action Level	30 ppb	

Weather Data Range from Full Weather Station		Wind Direction	S	Relative Humidity (%)	47.7 - 91.1	Daily Rain (in)	0.22	Landfill Perimeter Monitoring
Temp (°F)	44.0 - 59.3	Wind Speed (MPH)	0.2 - 12.9	Barometer (inHg)	29.45 - 30.04			

*Note: Wind Direction reported in the direction that it is coming from

Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-1		0.8	1.8	11:36	SSW
MS-2		0.8	1.8	0:04	S
MS-3		0.0	0.0	0:03	SW




Air Monitoring Notes:

Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT AT OR NEAR PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey			11/27/22	
				Field Operations	
				Page 1 of 1 Submitted By:	Rev. No. 0
				30 Minute Avg H ₂ S Action Level	30 ppb

Weather Data Range from Full Weather Station		Wind Direction	S	Relative Humidity (%)	47.7 - 91.1	Daily Rain (in)	0.22	Landfill Perimeter Monitoring
Temp (°F)	44.0 - 59.3	Wind Speed (MPH)	0.2 - 12.9	Barometer (inHg)	29.45 - 30.04			

*Note: Wind Direction reported in the direction that it is coming from


Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-4		0.1	3.0	18:22	S
MS-5		0.9	2.0	0:05	S
MS-6		0.9	2.0	11:09	SSW
MS-7		0.4	1.0	0:19	ESE
MS-8		0.0	0.0	0:05	SW



Air Monitoring Notes:


MS1 H2S MONITORING RESULTS - 11/27/22

NON-PROPERTY LINE MONITOR




MS2 H2S MONITORING RESULTS - 11/27/22

NON-PROPERTY LINE MONITOR




MS3 H2S MONITORING RESULTS - 11/27/22

NON-PROPERTY LINE MONITOR




MS4 H2S MONITORING RESULTS - 11/27/22

AT OR NEAR PROPERTY LINE




MS5 H2S MONITORING RESULTS - 11/27/22

AT OR NEAR PROPERTY LINE




MS6 H2S MONITORING RESULTS - 11/27/22

AT OR NEAR PROPERTY LINE



MS7 H2S MONITORING RESULTS - 11/27/22

AT OR NEAR PROPERTY LINE



MS8 H2S MONITORING RESULTS - 11/27/22

AT OR NEAR PROPERTY LINE

