


Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT NON-PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey				12/07/19	
					Field Operations	
					Page 1 of 1	Rev. No. 0
					Submitted By:	
				30 Minute Avg H ₂ S Action Level	30 ppb	

Weather Data Range from Full Weather Station		Wind Direction	NNW	Relative Humidity (%)	34.0 - 63.9	Daily Rain (in)	0.00	Landfill Perimeter Monitoring
Temp (°F)	27.7 - 39.5	Wind Speed (MPH)	0.2 - 15.2	Barometer (inHg)	30.23 - 30.60			

*Note: Wind Direction reported in the direction that it is coming from

Station Location Work Area	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-1	0.2	1.0	7:13	WNW
MS-2	0.2	1.7	23:57	NNW
MS-3	0.9	4.0	15:26	NNW




Air Monitoring Notes:

Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT AT OR NEAR PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey	12/07/19	
		Field Operations	
		Page 1 of 1	Rev. No. 0
		Submitted By:	
		30 Minute Avg H ₂ S Action Level	30 ppb

Weather Data Range from Full Weather Station	Wind Direction	NNW	Relative Humidity (%)	34.0 - 63.9	Daily Rain (in)	0.00	Landfill Perimeter Monitoring
Temp (°F)	27.7 - 39.5	Wind Speed (MPH)	0.2 - 15.2	Barometer (inHg)			
				30.23 - 30.60			

*Note: Wind Direction reported in the direction that it is coming from


Station Location Work Area	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-4	0.0	0.0	23:58	N/A
MS-5	2.5	49.8	21:46	NNE
MS-6	2.6	3.7	21:31	NE
MS-7	0.3	1.0	11:57	NNW
MS-8	0.3	1.0	12:13	NNW



Air Monitoring Notes:


MS1 H2S MONITORING RESULTS - 12/07/19

NON-PROPERTY LINE MONITOR




MS2 H2S MONITORING RESULTS - 12/07/19

NON-PROPERTY LINE MONITOR




MS3 H2S MONITORING RESULTS - 12/07/19

NON-PROPERTY LINE MONITOR




MS4 H2S MONITORING RESULTS - 12/07/19

AT OR NEAR PROPERTY LINE




MS5 H2S MONITORING RESULTS - 12/07/19

AT OR NEAR PROPERTY LINE




MS6 H2S MONITORING RESULTS - 12/07/19

AT OR NEAR PROPERTY LINE



MS7 H2S MONITORING RESULTS - 12/07/19

AT OR NEAR PROPERTY LINE



MS8 H2S MONITORING RESULTS - 12/07/19

AT OR NEAR PROPERTY LINE

