


Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT NON-PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey	11/01/19	
		Field Operations	
		Page 1 of 1	Rev. No. 0
		Submitted By:	
		30 Minute Avg H ₂ S Action Level	30 ppb

Weather Data Range from Full Weather Station		Wind Direction	W	Relative Humidity (%)	31.8 - 83.1	Daily Rain (in)	0.10	Landfill Perimeter Monitoring
Temp (°F)	43.3 - 73.4	Wind Speed (MPH)	0.9 - 18.9	Barometer (inHg)	29.53 - 30.33			

*Note: Wind Direction reported in the direction that it is coming from

Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-1		0.0	0.0	0:00	SSW
MS-2		2.0	6.0	9:35	W
MS-3		2.4	5.2	17:12	SSW




Air Monitoring Notes:

Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT AT OR NEAR PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey	11/01/19	
		Field Operations	
		Page 1 of 1	Rev. No. 0
		Submitted By:	
		30 Minute Avg H ₂ S Action Level	30 ppb

Weather Data Range from Full Weather Station		Wind Direction	W	Relative Humidity (%)	31.8 - 83.1	Daily Rain (in)	0.10	Landfill Perimeter Monitoring
Temp (°F)	43.3 - 73.4	Wind Speed (MPH)	0.9 - 18.9	Barometer (inHg)	29.53 - 30.33			

*Note: Wind Direction reported in the direction that it is coming from


Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-4		0.0	0.0	0:00	SSW
MS-5		1.6	4.8	7:43	WSW
MS-6		2.7	5.2	12:26	NW
MS-7		0.0	0.0	23:59	SSW
MS-8		0.1	1.0	0:48	SSW



Air Monitoring Notes:


MS1 H2S MONITORING RESULTS - 11/01/19

NON-PROPERTY LINE MONITOR




MS2 H2S MONITORING RESULTS - 11/01/19

NON-PROPERTY LINE MONITOR




MS3 H2S MONITORING RESULTS - 11/01/19

NON-PROPERTY LINE MONITOR




MS4 H2S MONITORING RESULTS - 11/01/19

AT OR NEAR PROPERTY LINE




MS5 H2S MONITORING RESULTS - 11/01/19

AT OR NEAR PROPERTY LINE




MS6 H2S MONITORING RESULTS - 11/01/19

AT OR NEAR PROPERTY LINE



MS7 H2S MONITORING RESULTS - 11/01/19

AT OR NEAR PROPERTY LINE



MS8 H2S MONITORING RESULTS - 11/01/19

AT OR NEAR PROPERTY LINE

