


Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT NON-PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey				11/09/19	
					Field Operations	
					Page 1 of 1	Rev. No. 0
					Submitted By:	
				30 Minute Avg H ₂ S Action Level	30 ppb	

Weather Data Range from Full Weather Station		Wind Direction	SSW	Relative Humidity (%)	27.2 - 81.2	Daily Rain (in)	0.00	Landfill Perimeter Monitoring
Temp (°F)	23.4 - 41.7	Wind Speed (MPH)	0.2 - 10.6	Barometer (inHg)	30.25 - 30.46			

*Note: Wind Direction reported in the direction that it is coming from

Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-1		1.0	3.2	23:23	WNW
MS-2		7.5	93.0	22:58	NW
MS-3		1.8	26.2	22:56	NNE




Air Monitoring Notes:

Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT AT OR NEAR PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey	11/09/19	
		Field Operations	
		Page 1 of 1	Rev. No. 0
		Submitted By:	
		30 Minute Avg H ₂ S Action Level	30 ppb

Weather Data Range from Full Weather Station		Wind Direction	SSW	Relative Humidity (%)	27.2 - 81.2	Daily Rain (in)	0.00	Landfill Perimeter Monitoring
Temp (°F)	23.4 - 41.7	Wind Speed (MPH)	0.2 - 10.6	Barometer (inHg)	30.25 - 30.46			

*Note: Wind Direction reported in the direction that it is coming from


Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-4		0.0	0.0	0:00	NW
MS-5		3.0	6.0	13:33	NNW
MS-6		6.8	63.2	6:33	NNW
MS-7		3.4	44.0	6:41	N
MS-8		4.0	43.0	7:38	N



Air Monitoring Notes:


MS1 H2S MONITORING RESULTS - 11/09/19

NON-PROPERTY LINE MONITOR




MS2 H2S MONITORING RESULTS - 11/09/19

NON-PROPERTY LINE MONITOR




MS3 H2S MONITORING RESULTS - 11/09/19

NON-PROPERTY LINE MONITOR




MS4 H2S MONITORING RESULTS - 11/09/19

AT OR NEAR PROPERTY LINE




MS5 H2S MONITORING RESULTS - 11/09/19

AT OR NEAR PROPERTY LINE




MS6 H2S MONITORING RESULTS - 11/09/19

AT OR NEAR PROPERTY LINE



MS7 H2S MONITORING RESULTS - 11/09/19

AT OR NEAR PROPERTY LINE



MS8 H2S MONITORING RESULTS - 11/09/19

AT OR NEAR PROPERTY LINE

