


Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT NON-PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey				11/17/19	
					Field Operations	
					Page 1 of 1	Rev. No. 0
					Submitted By:	
				30 Minute Avg H ₂ S Action Level	30 ppb	

Weather Data Range from Full Weather Station		Wind Direction	NNE	Relative Humidity (%)	42.2 - 67.6	Daily Rain (in)	0.00	Landfill Perimeter Monitoring
Temp (°F)	28.4 - 42.6	Wind Speed (MPH)	4.0 - 18.6	Barometer (inHg)	30.10 - 30.53			

*Note: Wind Direction reported in the direction that it is coming from

Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-1		0.0	0.8	10:56	NE
MS-2		0.1	1.0	0:31	N
MS-3		0.0	0.0	23:59	NNE




Air Monitoring Notes:

Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT AT OR NEAR PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey	11/17/19	
		Field Operations	
		Page 1 of 1	Rev. No. 0
		Submitted By:	
		30 Minute Avg H ₂ S Action Level	30 ppb

Weather Data Range from Full Weather Station		Wind Direction	NNE	Relative Humidity (%)	42.2 - 67.6	Daily Rain (in)	0.00	Landfill Perimeter Monitoring
Temp (°F)	28.4 - 42.6	Wind Speed (MPH)	4.0 - 18.6	Barometer (inHg)	30.10 - 30.53			

*Note: Wind Direction reported in the direction that it is coming from


Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-4		0.0	0.0	0:03	NE
MS-5		20.9	43.7	15:27	NE
MS-6		5.8	29.3	15:26	NE
MS-7		0.1	1.0	0:20	NNE
MS-8		0.0	0.0	23:59	NNE



Air Monitoring Notes:


MS1 H2S MONITORING RESULTS - 11/17/19

NON-PROPERTY LINE MONITOR




MS2 H2S MONITORING RESULTS - 11/17/19

NON-PROPERTY LINE MONITOR




MS3 H2S MONITORING RESULTS - 11/17/19

NON-PROPERTY LINE MONITOR




MS4 H2S MONITORING RESULTS - 11/17/19

AT OR NEAR PROPERTY LINE




MS5 H2S MONITORING RESULTS - 11/17/19

AT OR NEAR PROPERTY LINE




MS6 H2S MONITORING RESULTS - 11/17/19

AT OR NEAR PROPERTY LINE



MS7 H2S MONITORING RESULTS - 11/17/19

AT OR NEAR PROPERTY LINE



MS8 H2S MONITORING RESULTS - 11/17/19

AT OR NEAR PROPERTY LINE

