


Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT NON-PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey	11/26/19	
		Field Operations	
		Page 1 of 1	Rev. No. 0
		Submitted By:	
		30 Minute Avg H ₂ S Action Level	30 ppb

Weather Data Range from Full Weather Station		Wind Direction	SSW	Relative Humidity (%)	38.4 - 91.8	Daily Rain (in)	0.00	Landfill Perimeter Monitoring
Temp (°F)	35.6 - 62.2	Wind Speed (MPH)	0.1 - 10.3	Barometer (inHg)	30.00 - 30.13			

*Note: Wind Direction reported in the direction that it is coming from

Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-1		27.2	124.0	18:49	SW
MS-2		15.8	76.0	6:26	WNW
MS-3		1.5	6.7	23:53	WNW




Air Monitoring Notes:

Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT AT OR NEAR PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey	11/26/19	
		Field Operations	
		Page 1 of 1	Rev. No. 0
		Submitted By:	
		30 Minute Avg H ₂ S Action Level	30 ppb

Weather Data Range from Full Weather Station		Wind Direction	SSW	Relative Humidity (%)	38.4 - 91.8	Daily Rain (in)	0.00	Landfill Perimeter Monitoring
Temp (°F)	35.6 - 62.2	Wind Speed (MPH)	0.1 - 10.3	Barometer (inHg)	30.00 - 30.13			

*Note: Wind Direction reported in the direction that it is coming from


Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-4		0.0	0.0	0:03	W
MS-5		0.9	2.3	23:58	NNW
MS-6		2.0	5.2	20:47	NNW
MS-7		0.3	2.3	21:50	SE
MS-8		1.2	4.5	7:29	S



Air Monitoring Notes:


MS1 H2S MONITORING RESULTS - 11/26/19

NON-PROPERTY LINE MONITOR




MS2 H2S MONITORING RESULTS - 11/26/19

NON-PROPERTY LINE MONITOR




MS3 H2S MONITORING RESULTS - 11/26/19

NON-PROPERTY LINE MONITOR




MS4 H2S MONITORING RESULTS - 11/26/19

AT OR NEAR PROPERTY LINE




MS5 H2S MONITORING RESULTS - 11/26/19

AT OR NEAR PROPERTY LINE




MS6 H2S MONITORING RESULTS - 11/26/19

AT OR NEAR PROPERTY LINE



MS7 H2S MONITORING RESULTS - 11/26/19

AT OR NEAR PROPERTY LINE



MS8 H2S MONITORING RESULTS - 11/26/19

AT OR NEAR PROPERTY LINE

