


Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT NON-PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey				10/08/19	
					Field Operations	
					Page 1 of 1	Rev. No. 0
					Submitted By:	
				30 Minute Avg H ₂ S Action Level	30 ppb	

Weather Data Range from Full Weather Station		Wind Direction	NE	Relative Humidity (%)	51.9 - 91.1	Daily Rain (in)	0.00	Landfill Perimeter Monitoring
Temp (°F)	57.7 - 64.2	Wind Speed (MPH)	2.6 - 13.9	Barometer (inHg)	30.26 - 30.34			

*Note: Wind Direction reported in the direction that it is coming from

Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-1		0.1	0.8	16:34	NE
MS-2		0.2	1.0	19:55	NE
MS-3		0.5	2.0	14:27	NNE




Air Monitoring Notes:

Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT AT OR NEAR PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey	10/08/19	
		Field Operations	
		Page 1 of 1	Rev. No. 0
		Submitted By:	
		30 Minute Avg H ₂ S Action Level	30 ppb

Weather Data Range from Full Weather Station		Wind Direction	NE	Relative Humidity (%)	51.9 - 91.1	Daily Rain (in)	0.00	Landfill Perimeter Monitoring
Temp (°F)	57.7 - 64.2	Wind Speed (MPH)	2.6 - 13.9	Barometer (inHg)	30.26 - 30.34			

*Note: Wind Direction reported in the direction that it is coming from


Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-4		0.0	0.0	0:01	ENE
MS-5		5.6	22.8	19:19	NE
MS-6		1.2	10.2	19:08	NE
MS-7		0.0	0.0	0:03	NE
MS-8		0.0	0.0	0:03	NNE



Air Monitoring Notes:


MS1 H2S MONITORING RESULTS - 10/08/19

NON-PROPERTY LINE MONITOR




MS2 H2S MONITORING RESULTS - 10/08/19

NON-PROPERTY LINE MONITOR




MS3 H2S MONITORING RESULTS - 10/08/19

NON-PROPERTY LINE MONITOR




MS4 H2S MONITORING RESULTS - 10/08/19

AT OR NEAR PROPERTY LINE




MS5 H2S MONITORING RESULTS - 10/08/19

AT OR NEAR PROPERTY LINE




MS6 H2S MONITORING RESULTS - 10/08/19

AT OR NEAR PROPERTY LINE



MS7 H2S MONITORING RESULTS - 10/08/19

AT OR NEAR PROPERTY LINE



30 Min Averages Raw Data Action Level

MS8 H2S MONITORING RESULTS - 10/08/19

AT OR NEAR PROPERTY LINE

