


Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT NON-PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey				10/29/19	
					Field Operations	
					Page 1 of 1	Rev. No. 0
					Submitted By:	
				30 Minute Avg H ₂ S Action Level	30 ppb	

Weather Data Range from Full Weather Station		Wind Direction	ENE	Relative Humidity (%)	83.0 - 93.5	Daily Rain (in)	0.00	Landfill Perimeter Monitoring
Temp (°F)	55.0 - 59.0	Wind Speed (MPH)	0.4 - 6.7	Barometer (inHg)	30.33 - 30.40			

*Note: Wind Direction reported in the direction that it is coming from

Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-1		0.0	0.0	0:02	ESE
MS-2		1.5	3.5	5:41	ENE
MS-3		0.0	0.0	0:04	ESE




Air Monitoring Notes:

Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT AT OR NEAR PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey			10/29/19	
				Field Operations	
				Page 1 of 1 Submitted By:	Rev. No. 0
				30 Minute Avg H ₂ S Action Level	30 ppb

Weather Data Range from Full Weather Station		Wind Direction	ENE	Relative Humidity (%)	83.0 - 93.5	Daily Rain (in)	0.00	Landfill Perimeter Monitoring
Temp (°F)	55.0 - 59.0	Wind Speed (MPH)	0.4 - 6.7	Barometer (inHg)	30.33 - 30.40			

*Note: Wind Direction reported in the direction that it is coming from


Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-4		0.0	0.0	0:02	E
MS-5		2.2	12.0	6:41	ENE
MS-6		2.6	19.7	7:46	E
MS-7		2.5	12.0	2:18	E
MS-8		0.4	7.8	2:22	E



Air Monitoring Notes:


MS1 H2S MONITORING RESULTS - 10/29/19

NON-PROPERTY LINE MONITOR




MS2 H2S MONITORING RESULTS - 10/29/19

NON-PROPERTY LINE MONITOR




MS3 H2S MONITORING RESULTS - 10/29/19

NON-PROPERTY LINE MONITOR




MS4 H2S MONITORING RESULTS - 10/29/19

AT OR NEAR PROPERTY LINE




MS5 H2S MONITORING RESULTS - 10/29/19

AT OR NEAR PROPERTY LINE




MS6 H2S MONITORING RESULTS - 10/29/19

AT OR NEAR PROPERTY LINE



MS7 H2S MONITORING RESULTS - 10/29/19

AT OR NEAR PROPERTY LINE



MS8 H2S MONITORING RESULTS - 10/29/19

AT OR NEAR PROPERTY LINE

