


Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT NON-PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey				09/30/19	
					Field Operations	
					Page 1 of 1	Rev. No. 0
					Submitted By:	
				30 Minute Avg H ₂ S Action Level	30 ppb	

Weather Data Range from Full Weather Station		Wind Direction	NE	Relative Humidity (%)	45.8 - 86.4	Daily Rain (in)	0.00	Landfill Perimeter Monitoring
Temp (°F)	60.9 - 72.5	Wind Speed (MPH)	0.7 - 11.2	Barometer (inHg)	30.30 - 30.42			

*Note: Wind Direction reported in the direction that it is coming from

Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-1		0.0	0.2	23:40	SE
MS-2		0.4	1.8	23:43	S
MS-3		0.0	1.0	15:18	S




Air Monitoring Notes:

Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT AT OR NEAR PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey			09/30/19	
				Field Operations	
				Page 1 of 1 Submitted By:	Rev. No. 0
				30 Minute Avg H ₂ S Action Level	30 ppb

Weather Data Range from Full Weather Station		Wind Direction	NE	Relative Humidity (%)	45.8 - 86.4	Daily Rain (in)	0.00	Landfill Perimeter Monitoring
Temp (°F)	60.9 - 72.5	Wind Speed (MPH)	0.7 - 11.2	Barometer (inHg)	30.30 - 30.42			

*Note: Wind Direction reported in the direction that it is coming from


Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-4		0.0	0.0	23:58	ENE
MS-5		2.2	10.0	7:24	NE
MS-6		1.4	8.2	7:52	NE
MS-7		0.2	2.8	13:41	ESE
MS-8		1.8	6.8	16:52	SSE



Air Monitoring Notes:


MS1 H2S MONITORING RESULTS - 09/30/19

NON-PROPERTY LINE MONITOR




MS2 H2S MONITORING RESULTS - 09/30/19

NON-PROPERTY LINE MONITOR




MS3 H2S MONITORING RESULTS - 09/30/19

NON-PROPERTY LINE MONITOR




MS4 H2S MONITORING RESULTS - 09/30/19

AT OR NEAR PROPERTY LINE




MS5 H2S MONITORING RESULTS - 09/30/19

AT OR NEAR PROPERTY LINE




MS6 H2S MONITORING RESULTS - 09/30/19

AT OR NEAR PROPERTY LINE



MS7 H2S MONITORING RESULTS - 09/30/19

AT OR NEAR PROPERTY LINE



MS8 H2S MONITORING RESULTS - 09/30/19

AT OR NEAR PROPERTY LINE

