


Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT NON-PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey				07/23/20	
					Field Operations	
					Page 1 of 1	Rev. No. 0
					Submitted By:	
				30 Minute Avg H ₂ S Action Level	30 ppb	

Weather Data Range from Full Weather Station		Wind Direction	SSW	Relative Humidity (%)	53.6 - 88.3	Daily Rain (in)	0.00	Landfill Perimeter Monitoring
Temp (°F)	73.0 - 89.2	Wind Speed (MPH)	0.2 - 10.9	Barometer (inHg)	30.03 - 30.13			

*Note: Wind Direction reported in the direction that it is coming from

Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-1		0.1	0.8	14:04	S
MS-2		0.0	0.0	0:01	W
MS-3		0.0	0.0	0:04	SW




Air Monitoring Notes:

Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT AT OR NEAR PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey		07/23/20	
			Field Operations	
			Page 1 of 1 Submitted By:	Rev. No. 0
			30 Minute Avg H ₂ S Action Level	30 ppb

Weather Data Range from Full Weather Station		Wind Direction	SSW	Relative Humidity (%)	53.6 - 88.3	Daily Rain (in)	0.00	Landfill Perimeter Monitoring
Temp (°F)	73.0 - 89.2	Wind Speed (MPH)	0.2 - 10.9	Barometer (inHg)	30.03 - 30.13			

*Note: Wind Direction reported in the direction that it is coming from


Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-4		0.0	0.0	0:02	W
MS-5		0.0	0.0	0:05	SSE
MS-6		0.8	3.0	15:11	SW
MS-7		0.0	0.0	0:00	WSW
MS-8		0.0	0.2	15:04	SSW



Air Monitoring Notes:


MS1 H2S MONITORING RESULTS - 07/23/20

NON-PROPERTY LINE MONITOR




MS2 H2S MONITORING RESULTS - 07/23/20

NON-PROPERTY LINE MONITOR




MS3 H2S MONITORING RESULTS - 07/23/20

NON-PROPERTY LINE MONITOR




MS4 H2S MONITORING RESULTS - 07/23/20

AT OR NEAR PROPERTY LINE




MS5 H2S MONITORING RESULTS - 07/23/20

AT OR NEAR PROPERTY LINE




MS6 H2S MONITORING RESULTS - 07/23/20

AT OR NEAR PROPERTY LINE



MS7 H2S MONITORING RESULTS - 07/23/20

AT OR NEAR PROPERTY LINE



MS8 H2S MONITORING RESULTS - 07/23/20

AT OR NEAR PROPERTY LINE

