


Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT NON-PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey				11/26/20	
					Field Operations	
					Page 1 of 1	Rev. No. 0
					Submitted By:	
				30 Minute Avg H ₂ S Action Level	30 ppb	

Weather Data Range from Full Weather Station		Wind Direction	SSW	Relative Humidity (%)	54.0 - 91.4	Daily Rain (in)	0.45	Landfill Perimeter Monitoring
Temp (°F)	52.1 - 65.8	Wind Speed (MPH)	0.1 - 10.6	Barometer (inHg)	30.02 - 30.23			

*Note: Wind Direction reported in the direction that it is coming from

Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-1		0.4	1.2	12:08	SSE
MS-2		1.5	3.0	0:05	SW
MS-3		0.0	0.0	0:06	S




Air Monitoring Notes:

Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT AT OR NEAR PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey			11/26/20	
				Field Operations	
				Page 1 of 1 Submitted By:	Rev. No. 0
				30 Minute Avg H ₂ S Action Level	30 ppb

Weather Data Range from Full Weather Station		Wind Direction	SSW	Relative Humidity (%)	54.0 - 91.4	Daily Rain (in)	0.45	Landfill Perimeter Monitoring
Temp (°F)	52.1 - 65.8	Wind Speed (MPH)	0.1 - 10.6	Barometer (inHg)	30.02 - 30.23			

*Note: Wind Direction reported in the direction that it is coming from


Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-4		0.3	1.7	14:48	WSW
MS-5		0.6	2.0	0:04	S
MS-6		0.3	2.0	0:04	S
MS-7		0.3	2.0	0:01	E
MS-8		0.2	1.5	0:04	S



Air Monitoring Notes:


MS1 H2S MONITORING RESULTS - 11/26/20

NON-PROPERTY LINE MONITOR




MS2 H2S MONITORING RESULTS - 11/26/20

NON-PROPERTY LINE MONITOR




MS3 H2S MONITORING RESULTS - 11/26/20

NON-PROPERTY LINE MONITOR




MS4 H2S MONITORING RESULTS - 11/26/20

AT OR NEAR PROPERTY LINE




MS5 H2S MONITORING RESULTS - 11/26/20

AT OR NEAR PROPERTY LINE




MS6 H2S MONITORING RESULTS - 11/26/20

AT OR NEAR PROPERTY LINE



MS7 H2S MONITORING RESULTS - 11/26/20

AT OR NEAR PROPERTY LINE



MS8 H2S MONITORING RESULTS - 11/26/20

AT OR NEAR PROPERTY LINE

