


Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT NON-PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey				09/17/20	
					Field Operations	
					Page 1 of 1	Rev. No. 0
					Submitted By:	
				30 Minute Avg H ₂ S Action Level	30 ppb	

Weather Data Range from Full Weather Station		Wind Direction	SSW	Relative Humidity (%)	54.7 - 90.0	Daily Rain (in)	0.00	Landfill Perimeter Monitoring
Temp (°F)	60.9 - 76.6	Wind Speed (MPH)	0.1 - 8.9	Barometer (inHg)	30.02 - 30.20			

*Note: Wind Direction reported in the direction that it is coming from

Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-1		0.0	0.7	11:00	S
MS-2		0.0	0.2	21:14	W
MS-3		0.0	0.0	0:05	SW




Air Monitoring Notes:

Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT AT OR NEAR PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey	09/17/20	
		Field Operations	
		Page 1 of 1 Submitted By:	Rev. No. 0
		30 Minute Avg H ₂ S Action Level	30 ppb

Weather Data Range from Full Weather Station		Wind Direction	SSW	Relative Humidity (%)	54.7 - 90.0	Daily Rain (in)	0.00	Landfill Perimeter Monitoring
Temp (°F)	60.9 - 76.6	Wind Speed (MPH)	0.1 - 8.9	Barometer (inHg)	30.02 - 30.20			

*Note: Wind Direction reported in the direction that it is coming from


Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-4		0.0	0.7	11:45	SW
MS-5		0.0	0.0	0:04	SSW
MS-6		0.7	2.2	15:26	SSW
MS-7		0.0	0.0	0:03	SSE
MS-8		0.0	0.2	15:26	SW



Air Monitoring Notes:


MS1 H2S MONITORING RESULTS - 09/17/20

NON-PROPERTY LINE MONITOR




MS2 H2S MONITORING RESULTS - 09/17/20

NON-PROPERTY LINE MONITOR




MS3 H2S MONITORING RESULTS - 09/17/20

NON-PROPERTY LINE MONITOR




MS4 H2S MONITORING RESULTS - 09/17/20

AT OR NEAR PROPERTY LINE




MS5 H2S MONITORING RESULTS - 09/17/20

AT OR NEAR PROPERTY LINE




MS6 H2S MONITORING RESULTS - 09/17/20

AT OR NEAR PROPERTY LINE



MS7 H2S MONITORING RESULTS - 09/17/20

AT OR NEAR PROPERTY LINE



MS8 H2S MONITORING RESULTS - 09/17/20

AT OR NEAR PROPERTY LINE

