


Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT NON-PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey				09/23/20	
					Field Operations	
					Page 1 of 1	Rev. No. 0
					Submitted By:	
				30 Minute Avg H ₂ S Action Level	30 ppb	

Weather Data Range from Full Weather Station		Wind Direction	N	Relative Humidity (%)	33.9 - 77.4	Daily Rain (in)	0.00	Landfill Perimeter Monitoring
Temp (°F)	55.7 - 81.1	Wind Speed (MPH)	0.1 - 11.2	Barometer (inHg)	29.90 - 30.00			

*Note: Wind Direction reported in the direction that it is coming from

Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-1		0.1	1.0	6:42	S
MS-2		0.1	0.8	7:11	SW
MS-3		0.0	0.0	0:03	WNW




Air Monitoring Notes:

Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT AT OR NEAR PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey			09/23/20	
				Field Operations	
				Page 1 of 1 Submitted By:	Rev. No. 0
				30 Minute Avg H ₂ S Action Level	30 ppb

Weather Data Range from Full Weather Station		Wind Direction	N	Relative Humidity (%)	33.9 - 77.4	Daily Rain (in)	0.00	Landfill Perimeter Monitoring
Temp (°F)	55.7 - 81.1	Wind Speed (MPH)	0.1 - 11.2	Barometer (inHg)	29.90 - 30.00			

*Note: Wind Direction reported in the direction that it is coming from


Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-4		0.1	1.0	8:26	SW
MS-5		0.0	0.0	0:01	N
MS-6		0.9	3.0	11:31	NW
MS-7		0.0	0.0	0:00	SSW
MS-8		0.3	1.0	10:31	SW



Air Monitoring Notes:


MS1 H2S MONITORING RESULTS - 09/23/20

NON-PROPERTY LINE MONITOR




MS2 H2S MONITORING RESULTS - 09/23/20

NON-PROPERTY LINE MONITOR




MS3 H2S MONITORING RESULTS - 09/23/20

NON-PROPERTY LINE MONITOR




MS4 H2S MONITORING RESULTS - 09/23/20

AT OR NEAR PROPERTY LINE




MS5 H2S MONITORING RESULTS - 09/23/20

AT OR NEAR PROPERTY LINE




MS6 H2S MONITORING RESULTS - 09/23/20

AT OR NEAR PROPERTY LINE



MS7 H2S MONITORING RESULTS - 09/23/20

AT OR NEAR PROPERTY LINE



MS8 H2S MONITORING RESULTS - 09/23/20

AT OR NEAR PROPERTY LINE

