


Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT NON-PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey				12/17/21	
					Field Operations	
					Page 1 of 1	Rev. No. 0
					Submitted By:	
				30 Minute Avg H ₂ S Action Level	30 ppb	

Weather Data Range from Full Weather Station		Wind Direction	SSW	Relative Humidity (%)	14.9 - 66.6	Daily Rain (in)	4.60	Landfill Perimeter Monitoring
Temp (°F)	46.9 - 60.4	Wind Speed (MPH)	0.4 - 10.3	Barometer (inHg)	29.94 - 30.28			

*Note: Wind Direction reported in the direction that it is coming from

Station Location Work Area	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-1	1.3	3.2	17:13	W
MS-2	0.0	0.0	0:06	SSW
MS-3	0.0	0.0	0:01	SSW




Air Monitoring Notes:

Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT AT OR NEAR PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey		12/17/21	
			Field Operations	
			Page 1 of 1	Rev. No. 0
			Submitted By:	
		30 Minute Avg H ₂ S Action Level	30 ppb	

Weather Data Range from Full Weather Station	Wind Direction	SSW	Relative Humidity (%)	14.9 - 66.6	Daily Rain (in)	4.60	Landfill Perimeter Monitoring
Temp (°F)	46.9 - 60.4	Wind Speed (MPH)	0.4 - 10.3	Barometer (inHg)			
				29.94 - 30.28			

*Note: Wind Direction reported in the direction that it is coming from


Station Location Work Area	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-4	0.1	0.8	10:41	W
MS-5	0.0	0.0	0:05	SW
MS-6	1.0	2.0	4:41	S
MS-7	1.3	2.0	1:49	SE
MS-8	0.0	0.0	0:04	SW



Air Monitoring Notes:


MS1 H2S MONITORING RESULTS - 12/17/21

NON-PROPERTY LINE MONITOR




MS2 H2S MONITORING RESULTS - 12/17/21

NON-PROPERTY LINE MONITOR




MS3 H2S MONITORING RESULTS - 12/17/21

NON-PROPERTY LINE MONITOR




MS4 H2S MONITORING RESULTS - 12/17/21
AT OR NEAR PROPERTY LINE




MS5 H2S MONITORING RESULTS - 12/17/21

AT OR NEAR PROPERTY LINE




MS6 H2S MONITORING RESULTS - 12/17/21

AT OR NEAR PROPERTY LINE



MS7 H2S MONITORING RESULTS - 12/17/21
AT OR NEAR PROPERTY LINE



MS8 H2S MONITORING RESULTS - 12/17/21
AT OR NEAR PROPERTY LINE

