


Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT NON-PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey				02/02/21	
					Field Operations	
					Page 1 of 1	Rev. No. 0
					Submitted By:	
				30 Minute Avg H ₂ S Action Level	30 ppb	

Weather Data Range from Full Weather Station		Wind Direction	NNE	Relative Humidity (%)	80.9 - 91.7	Daily Rain (in)	0.00	Landfill Perimeter Monitoring
Temp (°F)	30.4 - 33.0	Wind Speed (MPH)	2.7 - 18.0	Barometer (inHg)	29.47 - 29.63			

*Note: Wind Direction reported in the direction that it is coming from

Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-1		0.0	0.0	0:02	N
MS-2		0.2	1.0	11:14	N
MS-3		0.0	0.0	0:02	NNE




Air Monitoring Notes:

Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT AT OR NEAR PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey	02/02/21	
		Field Operations	
		Page 1 of 1 Submitted By:	Rev. No. 0
		30 Minute Avg H ₂ S Action Level	30 ppb

Weather Data Range from Full Weather Station		Wind Direction	NNE	Relative Humidity (%)	80.9 - 91.6	Daily Rain (in)	0.00	Landfill Perimeter Monitoring
Temp (°F)	30.4 - 33.0	Wind Speed (MPH)	2.7 - 18.0	Barometer (inHg)	29.47 - 29.63			

*Note: Wind Direction reported in the direction that it is coming from


Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-4		0.9	2.0	7:53	NNE
MS-5		0.0	0.0	0:01	NNE
MS-6		0.0	0.0	0:03	NNE
MS-7		0.8	2.8	18:50	WSW
MS-8		0.7	3.0	16:17	NNE



Air Monitoring Notes:


MS1 H2S MONITORING RESULTS - 02/02/21

NON-PROPERTY LINE MONITOR




MS2 H2S MONITORING RESULTS - 02/02/21

NON-PROPERTY LINE MONITOR




MS3 H2S MONITORING RESULTS - 02/02/21

NON-PROPERTY LINE MONITOR




MS4 H2S MONITORING RESULTS - 02/02/21

AT OR NEAR PROPERTY LINE




MS5 H2S MONITORING RESULTS - 02/02/21

AT OR NEAR PROPERTY LINE




MS6 H2S MONITORING RESULTS - 02/02/21

AT OR NEAR PROPERTY LINE



MS7 H2S MONITORING RESULTS - 02/02/21

AT OR NEAR PROPERTY LINE



MS8 H2S MONITORING RESULTS - 02/02/21

AT OR NEAR PROPERTY LINE

