


Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT NON-PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey				01/27/21	
					Field Operations	
					Page 1 of 1	Rev. No. 0
					Submitted By:	
				30 Minute Avg H ₂ S Action Level	30 ppb	

Weather Data Range from Full Weather Station		Wind Direction	N	Relative Humidity (%)	55.7 - 88.7	Daily Rain (in)	0.00	Landfill Perimeter Monitoring
Temp (°F)	30.8 - 37.5	Wind Speed (MPH)	0.2 - 13.7	Barometer (inHg)	29.94 - 30.20			

*Note: Wind Direction reported in the direction that it is coming from

Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-1		0.0	0.0	0:00	NNE
MS-2		2.5	4.0	11:51	NNW
MS-3		0.0	0.0	0:05	NNE




Air Monitoring Notes:

Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT AT OR NEAR PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey	01/27/21	
		Field Operations	
		Page 1 of 1	Rev. No. 0
		Submitted By:	
		30 Minute Avg H ₂ S Action Level	30 ppb

Weather Data Range from Full Weather Station		Wind Direction	N	Relative Humidity (%)	55.7 - 88.7	Daily Rain (in)	0.00	Landfill Perimeter Monitoring
Temp (°F)	30.8 - 37.5	Wind Speed (MPH)	0.2 - 13.7	Barometer (inHg)	29.94 - 30.20			

*Note: Wind Direction reported in the direction that it is coming from


Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-4		2.2	4.0	10:14	WNW
MS-5		0.0	0.0	23:59	NNE
MS-6		0.0	0.0	0:00	N
MS-7		0.6	2.0	0:40	W
MS-8		0.1	1.0	17:24	NNW



Air Monitoring Notes:


MS1 H2S MONITORING RESULTS - 01/27/21

NON-PROPERTY LINE MONITOR




MS2 H2S MONITORING RESULTS - 01/27/21

NON-PROPERTY LINE MONITOR




MS3 H2S MONITORING RESULTS - 01/27/21

NON-PROPERTY LINE MONITOR




MS4 H2S MONITORING RESULTS - 01/27/21

AT OR NEAR PROPERTY LINE




MS5 H2S MONITORING RESULTS - 01/27/21

AT OR NEAR PROPERTY LINE




MS6 H2S MONITORING RESULTS - 01/27/21

AT OR NEAR PROPERTY LINE



MS7 H2S MONITORING RESULTS - 01/27/21

AT OR NEAR PROPERTY LINE



MS8 H2S MONITORING RESULTS - 01/27/21

AT OR NEAR PROPERTY LINE

