


Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT NON-PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey				06/01/21	
					Field Operations	
					Page 1 of 1	Rev. No. 0
					Submitted By:	
				30 Minute Avg H ₂ S Action Level	30 ppb	

Weather Data Range from Full Weather Station		Wind Direction	SSW	Relative Humidity (%)	31.0 - 91.5	Daily Rain (in)	0.00	Landfill Perimeter Monitoring
Temp (°F)	51.4 - 77.9	Wind Speed (MPH)	0.1 - 7.7	Barometer (inHg)	30.28 - 30.36			

*Note: Wind Direction reported in the direction that it is coming from

Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-1		0.0	0.0	0:01	SSW
MS-2		2.3	4.3	20:42	W
MS-3		0.5	1.2	20:38	SW




Air Monitoring Notes:

Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT AT OR NEAR PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey	06/01/21	
		Field Operations	
		Page 1 of 1	Rev. No. 0
		Submitted By:	
		30 Minute Avg H ₂ S Action Level	30 ppb

Weather Data Range from Full Weather Station		Wind Direction	SSW	Relative Humidity (%)	31.0 - 91.5	Daily Rain (in)	0.00	Landfill Perimeter Monitoring
Temp (°F)	51.4 - 77.9	Wind Speed (MPH)	0.1 - 7.7	Barometer (inHg)	30.28 - 30.36			

*Note: Wind Direction reported in the direction that it is coming from


Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-4		0.7	2.0	12:31	WSW
MS-5		0.2	1.0	12:12	SW
MS-6		0.0	0.0	0:01	N
MS-7		0.0	0.0	23:59	NE
MS-8		0.4	1.0	7:59	ENE



Air Monitoring Notes:


MS1 H2S MONITORING RESULTS - 06/01/21

NON-PROPERTY LINE MONITOR




MS2 H2S MONITORING RESULTS - 06/01/21

NON-PROPERTY LINE MONITOR




MS3 H2S MONITORING RESULTS - 06/01/21

NON-PROPERTY LINE MONITOR




MS4 H2S MONITORING RESULTS - 06/01/21

AT OR NEAR PROPERTY LINE




MS5 H2S MONITORING RESULTS - 06/01/21

AT OR NEAR PROPERTY LINE




MS6 H2S MONITORING RESULTS - 06/01/21

AT OR NEAR PROPERTY LINE



MS7 H2S MONITORING RESULTS - 06/01/21

AT OR NEAR PROPERTY LINE



MS8 H2S MONITORING RESULTS - 06/01/21

AT OR NEAR PROPERTY LINE

