


Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT NON-PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey				06/28/21	
					Field Operations	
					Page 1 of 1	Rev. No. 0
					Submitted By:	
				30 Minute Avg H ₂ S Action Level	30 ppb	

Weather Data Range from Full Weather Station		Wind Direction	SSW	Relative Humidity (%)	40.5 - 79.1	Daily Rain (in)	0.00	Landfill Perimeter Monitoring
Temp (°F)	75.9 - 95.7	Wind Speed (MPH)	0.9 - 9.8	Barometer (inHg)	30.22 - 30.31			

*Note: Wind Direction reported in the direction that it is coming from

Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-1		0.0	0.0	0:05	S
MS-2		2.5	4.0	18:35	WSW
MS-3		0.6	2.0	19:21	SW




Air Monitoring Notes:

Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT AT OR NEAR PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey	06/28/21	
		Field Operations	
		Page 1 of 1	Rev. No. 0
		Submitted By:	
		30 Minute Avg H ₂ S Action Level	30 ppb

Weather Data Range from Full Weather Station		Wind Direction	SSW	Relative Humidity (%)	40.5 - 79.1	Daily Rain (in)	0.00	Landfill Perimeter Monitoring
Temp (°F)	75.9 - 95.7	Wind Speed (MPH)	0.9 - 9.8	Barometer (inHg)	30.22 - 30.31			

*Note: Wind Direction reported in the direction that it is coming from


Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-4		1.1	3.0	15:33	SW
MS-5		0.0	0.0	0:00	SSW
MS-6		0.0	0.0	0:01	SSW
MS-7		0.0	0.0	0:02	SE
MS-8		0.0	0.0	0:02	SSW



Air Monitoring Notes:


MS1 H2S MONITORING RESULTS - 06/28/21

NON-PROPERTY LINE MONITOR




MS2 H2S MONITORING RESULTS - 06/28/21

NON-PROPERTY LINE MONITOR




MS3 H2S MONITORING RESULTS - 06/28/21

NON-PROPERTY LINE MONITOR




MS4 H2S MONITORING RESULTS - 06/28/21

AT OR NEAR PROPERTY LINE




MS5 H2S MONITORING RESULTS - 06/28/21

AT OR NEAR PROPERTY LINE




MS6 H2S MONITORING RESULTS - 06/28/21

AT OR NEAR PROPERTY LINE



MS7 H2S MONITORING RESULTS - 06/28/21

AT OR NEAR PROPERTY LINE



MS8 H2S MONITORING RESULTS - 06/28/21

AT OR NEAR PROPERTY LINE

