


Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT NON-PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey				05/07/21	
					Field Operations	
					Page 1 of 1	Rev. No. 0
					Submitted By:	
				30 Minute Avg H ₂ S Action Level	30 ppb	

Weather Data Range from Full Weather Station		Wind Direction	NE	Relative Humidity (%)	31.3 - 67.1	Daily Rain (in)	0.00	Landfill Perimeter Monitoring
Temp (°F)	48.0 - 65.6	Wind Speed (MPH)	0.3 - 11.1	Barometer (inHg)	29.92 - 30.04			

*Note: Wind Direction reported in the direction that it is coming from

Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-1		0.0	0.0	0:01	ESE
MS-2		1.8	3.0	13:43	SSW
MS-3		0.5	1.8	14:04	SE




Air Monitoring Notes:

Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT AT OR NEAR PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey	05/07/21	
		Field Operations	
		Page 1 of 1	Rev. No. 0
		Submitted By:	
		30 Minute Avg H ₂ S Action Level	30 ppb

Weather Data Range from Full Weather Station		Wind Direction	NE	Relative Humidity (%)	31.3 - 67.1	Daily Rain (in)	0.00	Landfill Perimeter Monitoring
Temp (°F)	48.0 - 65.6	Wind Speed (MPH)	0.3 - 11.1	Barometer (inHg)	29.92 - 30.04			

*Note: Wind Direction reported in the direction that it is coming from


Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-4		1.8	3.0	11:49	NE
MS-5		1.6	2.3	14:15	S
MS-6		0.0	0.0	0:04	N
MS-7		0.0	0.2	7:06	WSW
MS-8		0.1	0.8	12:27	E



Air Monitoring Notes:


MS1 H2S MONITORING RESULTS - 05/07/21

NON-PROPERTY LINE MONITOR




MS2 H2S MONITORING RESULTS - 05/07/21

NON-PROPERTY LINE MONITOR




MS3 H2S MONITORING RESULTS - 05/07/21

NON-PROPERTY LINE MONITOR




MS4 H2S MONITORING RESULTS - 05/07/21

AT OR NEAR PROPERTY LINE




MS5 H2S MONITORING RESULTS - 05/07/21

AT OR NEAR PROPERTY LINE




MS6 H2S MONITORING RESULTS - 05/07/21

AT OR NEAR PROPERTY LINE



MS7 H2S MONITORING RESULTS - 05/07/21

AT OR NEAR PROPERTY LINE



MS8 H2S MONITORING RESULTS - 05/07/21

AT OR NEAR PROPERTY LINE

