


Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT NON-PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey				11/26/21	
					Field Operations	
					Page 1 of 1	Rev. No. 0
					Submitted By:	
				30 Minute Avg H ₂ S Action Level	30 ppb	

Weather Data Range from Full Weather Station		Wind Direction	SW	Relative Humidity (%)	40.1 - 84.6	Daily Rain (in)	4.40	Landfill Perimeter Monitoring
Temp (°F)	37.0 - 47.6	Wind Speed (MPH)	0.2 - 14.7	Barometer (inHg)	29.68 - 29.86			

*Note: Wind Direction reported in the direction that it is coming from

Station Location Work Area	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-1	0.2	2.0	0:26	SSW
MS-2	0.0	0.0	0:02	SSW
MS-3	0.0	0.0	0:02	WSW




Air Monitoring Notes:

Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT AT OR NEAR PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey			11/26/21	
				Field Operations	
				Page 1 of 1	Rev. No. 0
				Submitted By:	
				30 Minute Avg H ₂ S Action Level	30 ppb

Weather Data Range from Full Weather Station	Wind Direction	SW	Relative Humidity (%)	40.1 - 84.6	Daily Rain (in)	4.40	Landfill Perimeter Monitoring
Temp (°F)	37.0 - 47.6	Wind Speed (MPH)	0.2 - 14.7	Barometer (inHg)			

*Note: Wind Direction reported in the direction that it is coming from


Station Location Work Area	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-4	0.3	6.5	0:01	WSW
MS-5	0.0	0.0	0:00	SSE
MS-6	0.7	2.5	0:41	S
MS-7	1.4	3.0	0:18	ESE
MS-8	0.0	0.0	0:00	SW



Air Monitoring Notes:


MS1 H2S MONITORING RESULTS - 11/26/21

NON-PROPERTY LINE MONITOR




MS2 H2S MONITORING RESULTS - 11/26/21

NON-PROPERTY LINE MONITOR




MS3 H2S MONITORING RESULTS - 11/26/21

NON-PROPERTY LINE MONITOR




MS4 H2S MONITORING RESULTS - 11/26/21
AT OR NEAR PROPERTY LINE




MS5 H2S MONITORING RESULTS - 11/26/21

AT OR NEAR PROPERTY LINE




MS6 H2S MONITORING RESULTS - 11/26/21

AT OR NEAR PROPERTY LINE



MS7 H2S MONITORING RESULTS - 11/26/21
AT OR NEAR PROPERTY LINE



MS8 H2S MONITORING RESULTS - 11/26/21
AT OR NEAR PROPERTY LINE

