


Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT NON-PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey				10/07/21	
					Field Operations	
					Page 1 of 1	Rev. No. 0
					Submitted By:	
				30 Minute Avg H ₂ S Action Level	30 ppb	

Weather Data Range from Full Weather Station		Wind Direction	NE	Relative Humidity (%)	48.9 - 91.4	Daily Rain (in)	0.21	Landfill Perimeter Monitoring
Temp (°F)	59.9 - 77.0	Wind Speed (MPH)	0.1 - 5.4	Barometer (inHg)	30.26 - 30.41			

*Note: Wind Direction reported in the direction that it is coming from

Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-1		0.0	0.5	20:53	NNE
MS-2		0.0	0.0	0:02	WNW
MS-3		0.0	0.0	0:05	NW




Air Monitoring Notes:

Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT AT OR NEAR PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey	10/07/21	
		Field Operations	
		Page 1 of 1	Rev. No. 0
		Submitted By:	
		30 Minute Avg H ₂ S Action Level	30 ppb

Weather Data Range from Full Weather Station		Wind Direction	NE	Relative Humidity (%)	48.9 - 91.4	Daily Rain (in)	0.21	Landfill Perimeter Monitoring
Temp (°F)	59.9 - 77.0	Wind Speed (MPH)	0.1 - 5.4	Barometer (inHg)	30.26 - 30.41			

*Note: Wind Direction reported in the direction that it is coming from


Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-4		0.0	0.0	0:04	ENE
MS-5		0.4	1.2	12:19	NNE
MS-6		0.0	0.0	0:02	N
MS-7		0.0	0.0	0:04	NNW
MS-8		0.0	0.2	9:00	SSW



Air Monitoring Notes:


MS1 H2S MONITORING RESULTS - 10/07/21

NON-PROPERTY LINE MONITOR




MS2 H2S MONITORING RESULTS - 10/07/21

NON-PROPERTY LINE MONITOR




MS3 H2S MONITORING RESULTS - 10/07/21

NON-PROPERTY LINE MONITOR




MS4 H2S MONITORING RESULTS - 10/07/21

AT OR NEAR PROPERTY LINE




MS5 H2S MONITORING RESULTS - 10/07/21

AT OR NEAR PROPERTY LINE




MS6 H2S MONITORING RESULTS - 10/07/21

AT OR NEAR PROPERTY LINE



MS7 H2S MONITORING RESULTS - 10/07/21

AT OR NEAR PROPERTY LINE



MS8 H2S MONITORING RESULTS - 10/07/21

AT OR NEAR PROPERTY LINE

