


Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT NON-PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey				10/26/21	
					Field Operations	
					Page 1 of 1	Rev. No. 0
					Submitted By:	
				30 Minute Avg H ₂ S Action Level	30 ppb	

Weather Data Range from Full Weather Station		Wind Direction	NE	Relative Humidity (%)	70.4 - 92.0	Daily Rain (in)	3.12	Landfill Perimeter Monitoring
Temp (°F)	55.4 - 63.3	Wind Speed (MPH)	0.4 - 17.3	Barometer (inHg)	29.40 - 29.79			

*Note: Wind Direction reported in the direction that it is coming from

Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-1		0.0	0.0	0:00	ENE
MS-2		0.0	0.0	0:01	ENE
MS-3		0.0	0.0	0:03	NNE




Air Monitoring Notes:

Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT AT OR NEAR PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey	10/26/21	
		Field Operations	
		Page 1 of 1	Rev. No. 0
		Submitted By:	
		30 Minute Avg H ₂ S Action Level	30 ppb

Weather Data Range from Full Weather Station		Wind Direction	NE	Relative Humidity (%)	70.4 - 92.0	Daily Rain (in)	3.12	Landfill Perimeter Monitoring
Temp (°F)	55.4 - 63.3	Wind Speed (MPH)	0.4 - 17.3	Barometer (inHg)	29.40 - 29.79			

*Note: Wind Direction reported in the direction that it is coming from


Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-4		0.0	0.0	0:01	E
MS-5		0.0	0.0	0:00	ENE
MS-6		0.3	1.2	10:16	SE
MS-7		0.0	0.8	10:52	SE
MS-8		0.0	0.0	0:00	NE



Air Monitoring Notes:


MS1 H2S MONITORING RESULTS - 10/26/21

NON-PROPERTY LINE MONITOR




MS2 H2S MONITORING RESULTS - 10/26/21

NON-PROPERTY LINE MONITOR




MS3 H2S MONITORING RESULTS - 10/26/21

NON-PROPERTY LINE MONITOR




MS4 H2S MONITORING RESULTS - 10/26/21

AT OR NEAR PROPERTY LINE




MS5 H2S MONITORING RESULTS - 10/26/21

AT OR NEAR PROPERTY LINE




MS6 H2S MONITORING RESULTS - 10/26/21

AT OR NEAR PROPERTY LINE



MS7 H2S MONITORING RESULTS - 10/26/21

AT OR NEAR PROPERTY LINE



MS8 H2S MONITORING RESULTS - 10/26/21

AT OR NEAR PROPERTY LINE

