


Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT NON-PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey				09/07/21	
					Field Operations	
					Page 1 of 1	Rev. No. 0
					Submitted By:	
				30 Minute Avg H ₂ S Action Level	30 ppb	

Weather Data Range from Full Weather Station		Wind Direction	SSW	Relative Humidity (%)	33.0 - 85.9	Daily Rain (in)	11.50	Landfill Perimeter Monitoring
Temp (°F)	0.0 - 81.8	Wind Speed (MPH)	0.2 - 7.7	Barometer (inHg)	29.98 - 30.08			

*Note: Wind Direction reported in the direction that it is coming from

Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-1		0.0	0.0	0:03	S
MS-2		0.0	0.0	0:03	W
MS-3		0.0	0.0	0:03	W




Air Monitoring Notes:

Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT AT OR NEAR PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey	09/07/21	
		Field Operations	
		Page 1 of 1	Rev. No. 0
		Submitted By:	
		30 Minute Avg H ₂ S Action Level	30 ppb

Weather Data Range from Full Weather Station	Wind Direction	SSW	Relative Humidity (%)	33.0 - 85.9	Daily Rain (in)	11.50	Landfill Perimeter Monitoring
Temp (°F)	0.0 - 81.8	Wind Speed (MPH)	0.2 - 7.7	Barometer (inHg)			
				29.98 - 30.08			

*Note: Wind Direction reported in the direction that it is coming from


Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-4		0.0	0.0	0:04	NE
MS-5		1.7	4.0	18:39	S
MS-6		0.0	0.0	0:03	NNE
MS-7		0.0	0.0	23:59	NW
MS-8		0.0	0.0	0:03	SSE



Air Monitoring Notes:


MS1 H2S MONITORING RESULTS - 09/07/21

NON-PROPERTY LINE MONITOR




MS2 H2S MONITORING RESULTS - 09/07/21

NON-PROPERTY LINE MONITOR




MS3 H2S MONITORING RESULTS - 09/07/21

NON-PROPERTY LINE MONITOR




MS4 H2S MONITORING RESULTS - 09/07/21

AT OR NEAR PROPERTY LINE




MS5 H2S MONITORING RESULTS - 09/07/21

AT OR NEAR PROPERTY LINE




MS6 H2S MONITORING RESULTS - 09/07/21

AT OR NEAR PROPERTY LINE



MS7 H2S MONITORING RESULTS - 09/07/21

AT OR NEAR PROPERTY LINE



MS8 H2S MONITORING RESULTS - 09/07/21

AT OR NEAR PROPERTY LINE

