


Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT NON-PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey				09/26/21	
					Field Operations	
					Page 1 of 1	Rev. No. 0
					Submitted By:	
				30 Minute Avg H ₂ S Action Level	30 ppb	

Weather Data Range from Full Weather Station		Wind Direction	N	Relative Humidity (%)	30.1 - 86.1	Daily Rain (in)	0.00	Landfill Perimeter Monitoring
Temp (°F)	59.3 - 73.7	Wind Speed (MPH)	0.2 - 12.3	Barometer (inHg)	29.92 - 30.05			

*Note: Wind Direction reported in the direction that it is coming from

Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-1		0.0	0.7	17:04	WNW
MS-2		0.0	0.0	0:01	WSW
MS-3		0.0	0.0	0:03	WSW




Air Monitoring Notes:

Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT AT OR NEAR PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey		09/26/21	
			Field Operations	
			Page 1 of 1	Rev. No. 0
			Submitted By:	
		30 Minute Avg H ₂ S Action Level	30 ppb	

Weather Data Range from Full Weather Station		Wind Direction	N	Relative Humidity (%)	30.1 - 86.1	Daily Rain (in)	0.00	Landfill Perimeter Monitoring
Temp (°F)	59.3 - 73.7	Wind Speed (MPH)	0.2 - 12.3	Barometer (inHg)	29.92 - 30.05			

*Note: Wind Direction reported in the direction that it is coming from


Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-4		0.0	0.0	0:00	SW
MS-5		0.0	0.8	16:31	N
MS-6		0.0	0.0	0:01	S
MS-7		0.0	0.5	15:28	S
MS-8		0.0	0.3	9:03	S



Air Monitoring Notes:


MS1 H2S MONITORING RESULTS - 09/26/21

NON-PROPERTY LINE MONITOR




MS2 H2S MONITORING RESULTS - 09/26/21

NON-PROPERTY LINE MONITOR




MS3 H2S MONITORING RESULTS - 09/26/21

NON-PROPERTY LINE MONITOR




MS4 H2S MONITORING RESULTS - 09/26/21

AT OR NEAR PROPERTY LINE




MS5 H2S MONITORING RESULTS - 09/26/21

AT OR NEAR PROPERTY LINE




MS6 H2S MONITORING RESULTS - 09/26/21

AT OR NEAR PROPERTY LINE



MS7 H2S MONITORING RESULTS - 09/26/21

AT OR NEAR PROPERTY LINE



MS8 H2S MONITORING RESULTS - 09/26/21

AT OR NEAR PROPERTY LINE

