


Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT NON-PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey				06/07/22	
					Field Operations	
					Page 1 of 1	Rev. No. 0
					Submitted By:	
				30 Minute Avg H ₂ S Action Level	30 ppb	

Weather Data Range from Full Weather Station		Wind Direction	SSW	Relative Humidity (%)	36.3 - 85.6	Daily Rain (in)	0.04	Landfill Perimeter Monitoring
Temp (°F)	61.3 - 79.8	Wind Speed (MPH)	0.8 - 12.7	Barometer (inHg)	30.01 - 30.16			

*Note: Wind Direction reported in the direction that it is coming from

Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-1		0.8	4.0	7:27	SW
MS-2		1.7	8.3	5:45	SW
MS-3		1.0	2.0	6:47	SW




Air Monitoring Notes:

Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT AT OR NEAR PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey	06/07/22	
		Field Operations	
		Page 1 of 1	Rev. No. 0
		Submitted By:	
		30 Minute Avg H ₂ S Action Level	30 ppb

Weather Data Range from Full Weather Station		Wind Direction	SSW	Relative Humidity (%)	36.6 - 85.6	Daily Rain (in)	0.04	Landfill Perimeter Monitoring
Temp (°F)	61.3 - 79.8	Wind Speed (MPH)	0.8 - 12.7	Barometer (inHg)	30.01 - 30.16			

*Note: Wind Direction reported in the direction that it is coming from


Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-4		0.0	0.2	7:36	SSW
MS-5		0.6	3.0	7:13	SSW
MS-6		0.0	0.0	0:01	SSW
MS-7		0.8	2.0	7:49	E
MS-8		1.9	3.0	8:13	SSW



Air Monitoring Notes:


MS1 H2S MONITORING RESULTS - 06/07/22

NON-PROPERTY LINE MONITOR




MS2 H2S MONITORING RESULTS - 06/07/22

NON-PROPERTY LINE MONITOR




MS3 H2S MONITORING RESULTS - 06/07/22

NON-PROPERTY LINE MONITOR




MS4 H2S MONITORING RESULTS - 06/07/22

AT OR NEAR PROPERTY LINE




MS5 H2S MONITORING RESULTS - 06/07/22

AT OR NEAR PROPERTY LINE




MS6 H2S MONITORING RESULTS - 06/07/22

AT OR NEAR PROPERTY LINE



MS7 H2S MONITORING RESULTS - 06/07/22

AT OR NEAR PROPERTY LINE



MS8 H2S MONITORING RESULTS - 06/07/22

AT OR NEAR PROPERTY LINE

