


Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT NON-PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey				09/01/22	
					Field Operations	
					Page 1 of 1	Rev. No. 0
					Submitted By:	
				30 Minute Avg H ₂ S Action Level	30 ppb	

Weather Data Range from Full Weather Station		Wind Direction	SSW	Relative Humidity (%)	22.2 - 60.5	Daily Rain (in)	0.00	Landfill Perimeter Monitoring
Temp (°F)	68.1 - 87.2	Wind Speed (MPH)	0.6 - 10.5	Barometer (inHg)	29.94 - 30.15			

*Note: Wind Direction reported in the direction that it is coming from

Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-1		0.6	1.0	2:13	SSW
MS-2		2.4	3.6	15:35	W
MS-3		0.0	0.0	0:01	SW




Air Monitoring Notes:

Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT AT OR NEAR PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey	09/01/22	
		Field Operations	
		Page 1 of 1	Rev. No. 0
		Submitted By:	
		30 Minute Avg H ₂ S Action Level	30 ppb

Weather Data Range from Full Weather Station		Wind Direction	SSW	Relative Humidity (%)	22.2 - 60.5	Daily Rain (in)	0.00	Landfill Perimeter Monitoring
Temp (°F)	68.1 - 87.2	Wind Speed (MPH)	0.6 - 10.5	Barometer (inHg)	29.94 - 30.15			

*Note: Wind Direction reported in the direction that it is coming from


Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-4		0.9	2.5	19:01	WSW
MS-5		0.5	1.5	6:44	SW
MS-6		0.6	2.0	5:27	SSW
MS-7		0.3	2.5	7:02	S
MS-8		0.7	2.0	12:51	S



Air Monitoring Notes:


MS1 H2S MONITORING RESULTS - 09/01/22

NON-PROPERTY LINE MONITOR




MS2 H2S MONITORING RESULTS - 09/01/22

NON-PROPERTY LINE MONITOR




MS3 H2S MONITORING RESULTS - 09/01/22

NON-PROPERTY LINE MONITOR




MS4 H2S MONITORING RESULTS - 09/01/22

AT OR NEAR PROPERTY LINE




MS5 H2S MONITORING RESULTS - 09/01/22

AT OR NEAR PROPERTY LINE




MS6 H2S MONITORING RESULTS - 09/01/22

AT OR NEAR PROPERTY LINE



MS7 H2S MONITORING RESULTS - 09/01/22

AT OR NEAR PROPERTY LINE



MS8 H2S MONITORING RESULTS - 09/01/22

AT OR NEAR PROPERTY LINE

