


Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT NON-PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey				04/09/22	
					Field Operations	
					Page 1 of 1	Rev. No. 0
					Submitted By:	
				30 Minute Avg H ₂ S Action Level	30 ppb	

Weather Data Range from Full Weather Station		Wind Direction	SW	Relative Humidity (%)	43.5 - 79.6	Daily Rain (in)	0.06	Landfill Perimeter Monitoring
Temp (°F)	46.9 - 57.0	Wind Speed (MPH)	0.2 - 12.5	Barometer (inHg)	29.68 - 29.78			

*Note: Wind Direction reported in the direction that it is coming from

Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-1		1.0	5.3	0:03	SSW
MS-2		3.2	8.2	6:02	WNW
MS-3		0.2	1.3	0:04	SSW




Air Monitoring Notes:

Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT AT OR NEAR PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey	04/09/22	
		Field Operations	
		Page 1 of 1	Rev. No. 0
		Submitted By:	
		30 Minute Avg H ₂ S Action Level	30 ppb

Weather Data Range from Full Weather Station		Wind Direction	SW	Relative Humidity (%)	43.5 - 79.6	Daily Rain (in)	0.06	Landfill Perimeter Monitoring
Temp (°F)	46.9 - 57.0	Wind Speed (MPH)	0.2 - 12.5	Barometer (inHg)	29.68 - 29.78			

*Note: Wind Direction reported in the direction that it is coming from


Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-4		0.3	1.3	0:02	SSW
MS-5		1.1	4.3	0:02	SW
MS-6		0.0	0.0	0:01	SSW
MS-7		1.3	3.0	9:41	SE
MS-8		0.0	0.0	0:05	SW



Air Monitoring Notes:


MS1 H2S MONITORING RESULTS - 04/09/22

NON-PROPERTY LINE MONITOR




MS2 H2S MONITORING RESULTS - 04/09/22

NON-PROPERTY LINE MONITOR




MS3 H2S MONITORING RESULTS - 04/09/22

NON-PROPERTY LINE MONITOR




MS4 H2S MONITORING RESULTS - 04/09/22

AT OR NEAR PROPERTY LINE




MS5 H2S MONITORING RESULTS - 04/09/22

AT OR NEAR PROPERTY LINE




MS6 H2S MONITORING RESULTS - 04/09/22

AT OR NEAR PROPERTY LINE



MS7 H2S MONITORING RESULTS - 04/09/22

AT OR NEAR PROPERTY LINE



MS8 H2S MONITORING RESULTS - 04/09/22

AT OR NEAR PROPERTY LINE

