


Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT NON-PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey				04/23/22	
					Field Operations	
					Page 1 of 1	Rev. No. 0
					Submitted By:	
				30 Minute Avg H ₂ S Action Level	30 ppb	

Weather Data Range from Full Weather Station		Wind Direction	NE	Relative Humidity (%)	27.0 - 67.3	Daily Rain (in)	0.00	Landfill Perimeter Monitoring
Temp (°F)	49.6 - 63.1	Wind Speed (MPH)	0.3 - 10.1	Barometer (inHg)	30.31 - 30.52			

*Note: Wind Direction reported in the direction that it is coming from

Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-1		1.6	2.8	21:30	ENE
MS-2		1.9	3.0	18:16	E
MS-3		0.0	0.5	13:36	ENE




Air Monitoring Notes:

Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT AT OR NEAR PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey	04/23/22	
		Field Operations	
		Page 1 of 1	Rev. No. 0
		Submitted By:	
		30 Minute Avg H ₂ S Action Level	30 ppb

Weather Data Range from Full Weather Station		Wind Direction	NE	Relative Humidity (%)	27.0 - 67.3	Daily Rain (in)	0.00	Landfill Perimeter Monitoring
Temp (°F)	49.6 - 63.1	Wind Speed (MPH)	0.3 - 10.1	Barometer (inHg)	30.31 - 30.52			

*Note: Wind Direction reported in the direction that it is coming from


Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-4		1.6	2.0	0:26	NNE
MS-5		1.3	2.0	3:41	NNE
MS-6		0.0	0.0	0:01	NE
MS-7		1.3	2.7	21:11	E
MS-8		2.5	4.0	10:10	E



Air Monitoring Notes:


MS1 H2S MONITORING RESULTS - 04/23/22

NON-PROPERTY LINE MONITOR




MS2 H2S MONITORING RESULTS - 04/23/22

NON-PROPERTY LINE MONITOR




MS3 H2S MONITORING RESULTS - 04/23/22

NON-PROPERTY LINE MONITOR




MS4 H2S MONITORING RESULTS - 04/23/22

AT OR NEAR PROPERTY LINE




MS5 H2S MONITORING RESULTS - 04/23/22

AT OR NEAR PROPERTY LINE




MS6 H2S MONITORING RESULTS - 04/23/22

AT OR NEAR PROPERTY LINE



MS7 H2S MONITORING RESULTS - 04/23/22

AT OR NEAR PROPERTY LINE



MS8 H2S MONITORING RESULTS - 04/23/22

AT OR NEAR PROPERTY LINE

