


Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT NON-PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey				08/03/22	
					Field Operations	
					Page 1 of 1	Rev. No. 0
					Submitted By:	
				30 Minute Avg H ₂ S Action Level	30 ppb	

Weather Data Range from Full Weather Station		Wind Direction	NNE	Relative Humidity (%)	24.7 - 83.2	Daily Rain (in)	0.00	Landfill Perimeter Monitoring
Temp (°F)	71.4 - 93.7	Wind Speed (MPH)	0.2 - 8.8	Barometer (inHg)	29.97 - 30.11			

*Note: Wind Direction reported in the direction that it is coming from

Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-1		0.3	2.0	23:45	NE
MS-2		4.0	12.5	23:03	E
MS-3		0.1	0.8	22:35	E




Air Monitoring Notes:

Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT AT OR NEAR PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey	08/03/22	
		Field Operations	
		Page 1 of 1	Rev. No. 0
		Submitted By:	
		30 Minute Avg H ₂ S Action Level	30 ppb

Weather Data Range from Full Weather Station		Wind Direction	NNE	Relative Humidity (%)	24.7 - 83.2	Daily Rain (in)	0.00	Landfill Perimeter Monitoring
Temp (°F)	71.4 - 93.7	Wind Speed (MPH)	0.2 - 8.8	Barometer (inHg)	29.97 - 30.11			

*Note: Wind Direction reported in the direction that it is coming from


Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-4		1.0	2.8	18:32	E
MS-5		0.7	2.0	17:32	E
MS-6		0.5	1.7	21:59	NNE
MS-7		0.1	1.0	8:29	NW
MS-8		2.0	6.0	18:20	NE



Air Monitoring Notes:


MS1 H2S MONITORING RESULTS - 08/03/22

NON-PROPERTY LINE MONITOR




MS2 H2S MONITORING RESULTS - 08/03/22

NON-PROPERTY LINE MONITOR




MS3 H2S MONITORING RESULTS - 08/03/22

NON-PROPERTY LINE MONITOR




MS4 H2S MONITORING RESULTS - 08/03/22

AT OR NEAR PROPERTY LINE




MS5 H2S MONITORING RESULTS - 08/03/22

AT OR NEAR PROPERTY LINE




MS6 H2S MONITORING RESULTS - 08/03/22

AT OR NEAR PROPERTY LINE



MS7 H2S MONITORING RESULTS - 08/03/22

AT OR NEAR PROPERTY LINE



MS8 H2S MONITORING RESULTS - 08/03/22

AT OR NEAR PROPERTY LINE

