


Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT NON-PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey				08/09/22	
					Field Operations	
					Page 1 of 1	Rev. No. 0
					Submitted By:	
				30 Minute Avg H ₂ S Action Level	30 ppb	

Weather Data Range from Full Weather Station		Wind Direction	SSW	Relative Humidity (%)	35.9 - 76.5	Daily Rain (in)	0.00	Landfill Perimeter Monitoring
Temp (°F)	82.0 - 99.1	Wind Speed (MPH)	0.3 - 10.0	Barometer (inHg)	29.94 - 30.05			

*Note: Wind Direction reported in the direction that it is coming from

Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-1		0.4	1.0	10:17	SW
MS-2		2.4	4.8	23:03	W
MS-3		0.0	0.2	5:45	SW




Air Monitoring Notes:

Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT AT OR NEAR PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey	08/09/22	
		Field Operations	
		Page 1 of 1	Rev. No. 0
		Submitted By:	
		30 Minute Avg H ₂ S Action Level	30 ppb

Weather Data Range from Full Weather Station		Wind Direction	SSW	Relative Humidity (%)	35.9 - 76.5	Daily Rain (in)	0.00	Landfill Perimeter Monitoring
Temp (°F)	82.0 - 99.1	Wind Speed (MPH)	0.3 - 10.0	Barometer (inHg)	29.94 - 30.05			

*Note: Wind Direction reported in the direction that it is coming from


Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-4		1.1	2.7	14:04	SW
MS-5		0.2	1.0	11:38	SW
MS-6		0.2	1.3	7:57	SW
MS-7		0.0	1.0	8:14	S
MS-8		1.5	3.0	10:14	SSW



Air Monitoring Notes:


MS1 H2S MONITORING RESULTS - 08/09/22

NON-PROPERTY LINE MONITOR




MS2 H2S MONITORING RESULTS - 08/09/22

NON-PROPERTY LINE MONITOR




MS3 H2S MONITORING RESULTS - 08/09/22

NON-PROPERTY LINE MONITOR




MS4 H2S MONITORING RESULTS - 08/09/22

AT OR NEAR PROPERTY LINE




MS5 H2S MONITORING RESULTS - 08/09/22

AT OR NEAR PROPERTY LINE




MS6 H2S MONITORING RESULTS - 08/09/22

AT OR NEAR PROPERTY LINE



MS7 H2S MONITORING RESULTS - 08/09/22

AT OR NEAR PROPERTY LINE



MS8 H2S MONITORING RESULTS - 08/09/22

AT OR NEAR PROPERTY LINE

