


Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT NON-PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey				12/20/22	
					Field Operations	
					Page 1 of 1	Rev. No. 0
					Submitted By:	
				30 Minute Avg H ₂ S Action Level	30 ppb	

Weather Data Range from Full Weather Station		Wind Direction	NNW	Relative Humidity (%)	40.1 - 66.8	Daily Rain (in)	0.00	Landfill Perimeter Monitoring
Temp (°F)	29.3 - 40.4	Wind Speed (MPH)	0.4 - 11.9	Barometer (inHg)	30.41 - 30.54			

*Note: Wind Direction reported in the direction that it is coming from

Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-1		1.7	4.0	7:50	SW
MS-2		0.0	0.0	23:59	WNW
MS-3		0.5	2.0	7:32	SW




Air Monitoring Notes:

Keegan Landfill Monitoring Project	DAILY AIR MONITORING REPORT AT OR NEAR PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey	12/20/22	
		Field Operations	
Page 1 of 1		Rev. No. 0	
Submitted By:			
		30 Minute Avg H ₂ S Action Level	30 ppb

Weather Data Range from Full Weather Station		Wind Direction	NNW	Relative Humidity (%)	40.1 - 66.8	Daily Rain (in)	0.00	Landfill Perimeter Monitoring
Temp (°F)	29.3 - 40.4	Wind Speed (MPH)	0.4 - 11.9	Barometer (inHg)	30.41 - 30.54			

*Note: Wind Direction reported in the direction that it is coming from


Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-4		1.0	3.0	7:12	WNW
MS-5		0.1	0.7	9:22	NNW
MS-6		0.0	0.0	0:01	NW
MS-7		0.0	0.8	9:25	W
MS-8		0.0	0.0	0:03	WNW



Air Monitoring Notes:


MS1 H2S MONITORING RESULTS - 12/20/22

NON-PROPERTY LINE MONITOR




MS2 H2S MONITORING RESULTS - 12/20/22

NON-PROPERTY LINE MONITOR




MS3 H2S MONITORING RESULTS - 12/20/22

NON-PROPERTY LINE MONITOR




MS4 H2S MONITORING RESULTS - 12/20/22

AT OR NEAR PROPERTY LINE




MS5 H2S MONITORING RESULTS - 12/20/22

AT OR NEAR PROPERTY LINE




MS6 H2S MONITORING RESULTS - 12/20/22

AT OR NEAR PROPERTY LINE



MS7 H2S MONITORING RESULTS - 12/20/22

AT OR NEAR PROPERTY LINE



MS8 H2S MONITORING RESULTS - 12/20/22

AT OR NEAR PROPERTY LINE

