


Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT NON-PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey	02/18/22	
		Field Operations	
		Page 1 of 1	Rev. No. 0
		Submitted By:	
		30 Minute Avg H ₂ S Action Level	30 ppb

Weather Data Range from Full Weather Station		Wind Direction	SSW	Relative Humidity (%)	27.6 - 81.2	Daily Rain (in)	7.25	Landfill Perimeter Monitoring
Temp (°F)	27.7 - 65.3	Wind Speed (MPH)	1.8 - 18.9	Barometer (inHg)	29.39 - 30.20			

*Note: Wind Direction reported in the direction that it is coming from

Station Location Work Area	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-1	0.3	1.3	0:15	SSW
MS-2	2.8	3.0	0:03	SSW
MS-3	0.2	1.0	14:40	N




Air Monitoring Notes:

Keegan Landfill Monitoring Project	DAILY AIR MONITORING REPORT AT OR NEAR PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey	02/18/22	
		Field Operations	
Page 1 of 1		Rev. No. 0	
Submitted By:			
		30 Minute Avg H ₂ S Action Level	30 ppb

Weather Data Range from Full Weather Station	Wind Direction	SSW	Relative Humidity (%)	27.6 - 81.2	Daily Rain (in)	7.25	Landfill Perimeter Monitoring
Temp (°F)	27.7 - 65.3	Wind Speed (MPH)	1.8 - 18.9	Barometer (inHg)			
				29.39 - 30.20			

*Note: Wind Direction reported in the direction that it is coming from


Station Location Work Area	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-4	1.6	3.8	13:51	W
MS-5	0.0	0.0	0:01	SSW
MS-6	0.0	0.7	1:13	SSW
MS-7	0.8	1.0	0:03	ESE
MS-8	0.0	0.0	0:01	SSW



Air Monitoring Notes:


MS1 H2S MONITORING RESULTS - 02/18/22

NON-PROPERTY LINE MONITOR




MS2 H2S MONITORING RESULTS - 02/18/22

NON-PROPERTY LINE MONITOR




MS3 H2S MONITORING RESULTS - 02/18/22

NON-PROPERTY LINE MONITOR




MS4 H₂S MONITORING RESULTS - 02/18/22
AT OR NEAR PROPERTY LINE




MS5 H2S MONITORING RESULTS - 02/18/22

AT OR NEAR PROPERTY LINE




MS6 H2S MONITORING RESULTS - 02/18/22

AT OR NEAR PROPERTY LINE



MS7 H2S MONITORING RESULTS - 02/18/22
AT OR NEAR PROPERTY LINE



MS8 H2S MONITORING RESULTS - 02/18/22

AT OR NEAR PROPERTY LINE

