


Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT NON-PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey				03/10/22	
					Field Operations	
					Page 1 of 1	Rev. No. 0
					Submitted By:	
				30 Minute Avg H ₂ S Action Level	30 ppb	

Weather Data Range from Full Weather Station		Wind Direction	NE	Relative Humidity (%)	35.1 - 90.8	Daily Rain (in)	8.72	Landfill Perimeter Monitoring
Temp (°F)	30.2 - 51.0	Wind Speed (MPH)	0.1 - 7.7	Barometer (inHg)	30.14 - 30.31			

*Note: Wind Direction reported in the direction that it is coming from

Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-1		2.4	5.0	17:20	ENE
MS-2		2.3	6.0	20:44	E
MS-3		0.0	0.0	0:02	NNW




Air Monitoring Notes:

Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT AT OR NEAR PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey	03/10/22	
		Field Operations	
		Page 1 of 1	Rev. No. 0
		Submitted By:	
		30 Minute Avg H ₂ S Action Level	30 ppb

Weather Data Range from Full Weather Station		Wind Direction	NE	Relative Humidity (%)	35.1 - 90.8	Daily Rain (in)	8.72	Landfill Perimeter Monitoring
Temp (°F)	30.2 - 51.0	Wind Speed (MPH)	0.1 - 7.7	Barometer (inHg)	30.14 - 30.31			

*Note: Wind Direction reported in the direction that it is coming from


Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-4		0.7	3.0	16:21	ENE
MS-5		0.0	0.0	0:03	NNE
MS-6		1.2	2.2	16:56	E
MS-7		1.5	3.8	17:11	NNW
MS-8		0.0	0.0	0:02	NE



Air Monitoring Notes:


MS1 H2S MONITORING RESULTS - 03/10/22

NON-PROPERTY LINE MONITOR




MS2 H2S MONITORING RESULTS - 03/10/22

NON-PROPERTY LINE MONITOR




MS3 H2S MONITORING RESULTS - 03/10/22

NON-PROPERTY LINE MONITOR




MS4 H2S MONITORING RESULTS - 03/10/22

AT OR NEAR PROPERTY LINE




MS5 H2S MONITORING RESULTS - 03/10/22

AT OR NEAR PROPERTY LINE




MS6 H2S MONITORING RESULTS - 03/10/22

AT OR NEAR PROPERTY LINE



MS7 H2S MONITORING RESULTS - 03/10/22

AT OR NEAR PROPERTY LINE



MS8 H2S MONITORING RESULTS - 03/10/22

AT OR NEAR PROPERTY LINE

