


Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT NON-PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey				03/27/22	
					Field Operations	
					Page 1 of 1	Rev. No. 0
					Submitted By:	
				30 Minute Avg H ₂ S Action Level	30 ppb	

Weather Data Range from Full Weather Station		Wind Direction	WNW	Relative Humidity (%)	32.1 - 71.0	Daily Rain (in)	9.30	Landfill Perimeter Monitoring
Temp (°F)	31.0 - 45.8	Wind Speed (MPH)	1.1 - 16.3	Barometer (inHg)	29.62 - 29.92			

*Note: Wind Direction reported in the direction that it is coming from

Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-1		0.1	1.0	12:15	WSW
MS-2		1.0	1.8	11:37	WNW
MS-3		0.2	1.0	12:47	SW




Air Monitoring Notes:

Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT AT OR NEAR PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey	03/27/22	
		Field Operations	
		Page 1 of 1	Rev. No. 0
		Submitted By:	
		30 Minute Avg H ₂ S Action Level	30 ppb

Weather Data Range from Full Weather Station		Wind Direction	WNW	Relative Humidity (%)	32.1 - 71.0	Daily Rain (in)	9.30	Landfill Perimeter Monitoring
Temp (°F)	31.0 - 45.8	Wind Speed (MPH)	1.1 - 16.3	Barometer (inHg)	29.62 - 29.92			

*Note: Wind Direction reported in the direction that it is coming from


Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-4		0.1	1.0	9:24	WNW
MS-5		0.0	0.0	0:03	W
MS-6		0.0	0.3	0:00	WNW
MS-7		1.0	1.5	5:12	S
MS-8		0.0	0.0	0:03	W



Air Monitoring Notes:


MS1 H2S MONITORING RESULTS - 03/27/22

NON-PROPERTY LINE MONITOR




MS2 H2S MONITORING RESULTS - 03/27/22

NON-PROPERTY LINE MONITOR




MS3 H2S MONITORING RESULTS - 03/27/22

NON-PROPERTY LINE MONITOR




MS4 H2S MONITORING RESULTS - 03/27/22

AT OR NEAR PROPERTY LINE




MS5 H2S MONITORING RESULTS - 03/27/22

AT OR NEAR PROPERTY LINE




MS6 H2S MONITORING RESULTS - 03/27/22

AT OR NEAR PROPERTY LINE



MS7 H2S MONITORING RESULTS - 03/27/22

AT OR NEAR PROPERTY LINE



MS8 H2S MONITORING RESULTS - 03/27/22

AT OR NEAR PROPERTY LINE

