


Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT NON-PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey	10/03/22	
		Field Operations	
		Page 1 of 1	Rev. No. 0
		Submitted By:	
		30 Minute Avg H ₂ S Action Level	30 ppb

Weather Data Range from Full Weather Station		Wind Direction	NNE	Relative Humidity (%)	41.4 - 81.5	Daily Rain (in)	0.42	Landfill Perimeter Monitoring
Temp (°F)	49.2 - 53.0	Wind Speed (MPH)	4.7 - 20.2	Barometer (inHg)	30.21 - 30.32			

*Note: Wind Direction reported in the direction that it is coming from

Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-1		0.4	1.8	19:02	NE
MS-2		0.4	1.5	19:20	NE
MS-3		0.0	0.0	0:00	NNE




Air Monitoring Notes:

Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT AT OR NEAR PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey	10/03/22	
		Field Operations	
		Page 1 of 1	Rev. No. 0
		Submitted By:	
		30 Minute Avg H ₂ S Action Level	30 ppb

Weather Data Range from Full Weather Station		Wind Direction	NNE	Relative Humidity (%)	43.1 - 81.5	Daily Rain (in)	0.42	Landfill Perimeter Monitoring
Temp (°F)	49.2 - 53.0	Wind Speed (MPH)	4.7 - 20.2	Barometer (inHg)	30.21 - 30.32			

*Note: Wind Direction reported in the direction that it is coming from


Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-4		0.0	0.0	0:01	ENE
MS-5		0.0	0.5	15:28	NNE
MS-6		0.5	1.7	11:22	NE
MS-7		0.0	0.8	23:28	WNW
MS-8		0.0	0.0	0:01	NE



Air Monitoring Notes:


MS1 H2S MONITORING RESULTS - 10/03/22

NON-PROPERTY LINE MONITOR




MS2 H2S MONITORING RESULTS - 10/03/22

NON-PROPERTY LINE MONITOR




MS3 H2S MONITORING RESULTS - 10/03/22

NON-PROPERTY LINE MONITOR




MS4 H2S MONITORING RESULTS - 10/03/22

AT OR NEAR PROPERTY LINE




MS5 H2S MONITORING RESULTS - 10/03/22

AT OR NEAR PROPERTY LINE




MS6 H2S MONITORING RESULTS - 10/03/22

AT OR NEAR PROPERTY LINE



MS7 H2S MONITORING RESULTS - 10/03/22

AT OR NEAR PROPERTY LINE



MS8 H2S MONITORING RESULTS - 10/03/22

AT OR NEAR PROPERTY LINE

