


Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT NON-PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey				10/07/22	
					Field Operations	
					Page 1 of 1	Rev. No. 0
					Submitted By:	
				30 Minute Avg H ₂ S Action Level	30 ppb	

Weather Data Range from Full Weather Station		Wind Direction	S	Relative Humidity (%)	33.3 - 90.0	Daily Rain (in)	0.00	Landfill Perimeter Monitoring
Temp (°F)	53.6 - 78.8	Wind Speed (MPH)	0.1 - 11.5	Barometer (inHg)	29.99 - 30.16			

*Note: Wind Direction reported in the direction that it is coming from

Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-1		0.5	2.8	9:40	SSW
MS-2		0.0	0.5	17:47	WSW
MS-3		0.0	0.0	0:01	WNW




Air Monitoring Notes:

Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT AT OR NEAR PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey	10/07/22	
		Field Operations	
		Page 1 of 1 Submitted By:	Rev. No. 0
		30 Minute Avg H ₂ S Action Level	30 ppb

Weather Data Range from Full Weather Station		Wind Direction	S	Relative Humidity (%)	33.3 - 90.0	Daily Rain (in)	0.00	Landfill Perimeter Monitoring
Temp (°F)	53.6 - 78.8	Wind Speed (MPH)	0.1 - 11.5	Barometer (inHg)	29.99 - 30.16			

*Note: Wind Direction reported in the direction that it is coming from


Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-4		0.3	1.0	11:33	WSW
MS-5		0.4	1.0	1:13	S
MS-6		1.2	3.0	9:34	SSW
MS-7		0.3	2.0	9:30	SSE
MS-8		0.4	1.8	16:42	SW



Air Monitoring Notes:


MS1 H2S MONITORING RESULTS - 10/07/22

NON-PROPERTY LINE MONITOR




MS2 H2S MONITORING RESULTS - 10/07/22

NON-PROPERTY LINE MONITOR




MS3 H2S MONITORING RESULTS - 10/07/22

NON-PROPERTY LINE MONITOR




MS4 H2S MONITORING RESULTS - 10/07/22

AT OR NEAR PROPERTY LINE




MS5 H2S MONITORING RESULTS - 10/07/22

AT OR NEAR PROPERTY LINE




MS6 H2S MONITORING RESULTS - 10/07/22

AT OR NEAR PROPERTY LINE



MS7 H2S MONITORING RESULTS - 10/07/22

AT OR NEAR PROPERTY LINE



MS8 H2S MONITORING RESULTS - 10/07/22

AT OR NEAR PROPERTY LINE

