


Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT NON-PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey	10/28/22	
		Field Operations	
		Page 1 of 1	Rev. No. 0
		Submitted By:	
		30 Minute Avg H ₂ S Action Level	30 ppb

Weather Data Range from Full Weather Station		Wind Direction	NNE	Relative Humidity (%)	31.5 - 74.1	Daily Rain (in)	0.00	Landfill Perimeter Monitoring
Temp (°F)	43.8 - 58.2	Wind Speed (MPH)	0.3 - 13.0	Barometer (inHg)	30.46 - 30.62			

*Note: Wind Direction reported in the direction that it is coming from

Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-1		0.9	3.5	19:15	NNE
MS-2		1.4	8.7	19:17	NE
MS-3		0.0	0.0	0:01	NNE




Air Monitoring Notes:

Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT AT OR NEAR PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey	10/28/22	
		Field Operations	
		Page 1 of 1	Rev. No. 0
		Submitted By:	
		30 Minute Avg H ₂ S Action Level	30 ppb

Weather Data Range from Full Weather Station		Wind Direction	NNE	Relative Humidity (%)	31.5 - 74.1	Daily Rain (in)	0.00	Landfill Perimeter Monitoring
Temp (°F)	43.8 - 58.2	Wind Speed (MPH)	0.3 - 13.0	Barometer (inHg)	30.46 - 30.62			

*Note: Wind Direction reported in the direction that it is coming from


Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-4		0.2	2.0	19:28	ENE
MS-5		0.8	3.8	19:39	NE
MS-6		1.0	4.0	19:25	NE
MS-7		0.4	2.0	19:26	NW
MS-8		0.0	0.0	0:05	NNE



Air Monitoring Notes:


MS1 H2S MONITORING RESULTS - 10/28/22

NON-PROPERTY LINE MONITOR




MS2 H2S MONITORING RESULTS - 10/28/22

NON-PROPERTY LINE MONITOR




MS3 H2S MONITORING RESULTS - 10/28/22

NON-PROPERTY LINE MONITOR




MS4 H2S MONITORING RESULTS - 10/28/22

AT OR NEAR PROPERTY LINE




MS5 H2S MONITORING RESULTS - 10/28/22

AT OR NEAR PROPERTY LINE




MS6 H2S MONITORING RESULTS - 10/28/22

AT OR NEAR PROPERTY LINE



MS7 H2S MONITORING RESULTS - 10/28/22

AT OR NEAR PROPERTY LINE



MS8 H2S MONITORING RESULTS - 10/28/22

AT OR NEAR PROPERTY LINE

