


Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT NON-PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey				03/07/23	
					Field Operations	
					Page 1 of 1	Rev. No. 0
					Submitted By:	
				30 Minute Avg H ₂ S Action Level	30 ppb	

Weather Data Range from Full Weather Station		Wind Direction	NNW	Relative Humidity (%)	25.1 - 86.4	Daily Rain (in)	0.02	Landfill Perimeter Monitoring
Temp (°F)	33.4 - 48.2	Wind Speed (MPH)	0.6 - 23.8	Barometer (inHg)	29.86 - 30.12			

*Note: Wind Direction reported in the direction that it is coming from

Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-1		0.5	1.0	0:02	WSW
MS-2		0.0	0.0	0:02	NW
MS-3		0.9	1.0	0:05	WSW




Air Monitoring Notes:

Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT AT OR NEAR PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey	03/07/23	
		Field Operations	
		Page 1 of 1	Rev. No. 0
		Submitted By:	
		30 Minute Avg H ₂ S Action Level	30 ppb

Weather Data Range from Full Weather Station		Wind Direction	NNW	Relative Humidity (%)	25.1 - 86.4	Daily Rain (in)	0.02	Landfill Perimeter Monitoring
Temp (°F)	33.4 - 48.2	Wind Speed (MPH)	0.6 - 23.8	Barometer (inHg)	29.86 - 30.12			

*Note: Wind Direction reported in the direction that it is coming from


Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-4		0.9	2.8	15:53	WNW
MS-5		2.0	3.5	6:05	NW
MS-6		0.0	0.0	0:04	NW
MS-7		0.0	1.0	7:56	WSW
MS-8		0.2	1.0	6:57	WNW



Air Monitoring Notes:


MS1 H2S MONITORING RESULTS - 03/07/23

NON-PROPERTY LINE MONITOR




MS2 H2S MONITORING RESULTS - 03/07/23

NON-PROPERTY LINE MONITOR




MS3 H2S MONITORING RESULTS - 03/07/23

NON-PROPERTY LINE MONITOR




MS4 H2S MONITORING RESULTS - 03/07/23

AT OR NEAR PROPERTY LINE




MS5 H2S MONITORING RESULTS - 03/07/23

AT OR NEAR PROPERTY LINE




MS6 H2S MONITORING RESULTS - 03/07/23

AT OR NEAR PROPERTY LINE



MS7 H2S MONITORING RESULTS - 03/07/23

AT OR NEAR PROPERTY LINE



MS8 H2S MONITORING RESULTS - 03/07/23

AT OR NEAR PROPERTY LINE

