


Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT NON-PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey				03/09/23	
					Field Operations	
					Page 1 of 1	Rev. No. 0
					Submitted By:	
				30 Minute Avg H ₂ S Action Level	30 ppb	

Weather Data Range from Full Weather Station		Wind Direction	NNW	Relative Humidity (%)	35.3 - 63.9	Daily Rain (in)	0.00	Landfill Perimeter Monitoring
Temp (°F)	33.6 - 51.9	Wind Speed (MPH)	0.7 - 15.7	Barometer (inHg)	30.19 - 30.30			

*Note: Wind Direction reported in the direction that it is coming from

Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-1		0.5	1.0	9:15	NW
MS-2		0.0	0.0	0:03	NNW
MS-3		0.9	1.0	0:03	N




Air Monitoring Notes:

Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT AT OR NEAR PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey	03/09/23	
		Field Operations	
		Page 1 of 1	Rev. No. 0
		Submitted By:	
		30 Minute Avg H ₂ S Action Level	30 ppb

Weather Data Range from Full Weather Station		Wind Direction	NNW	Relative Humidity (%)	35.3 - 63.9	Daily Rain (in)	0.00	Landfill Perimeter Monitoring
Temp (°F)	33.6 - 51.9	Wind Speed (MPH)	0.7 - 15.7	Barometer (inHg)	30.19 - 30.30			

*Note: Wind Direction reported in the direction that it is coming from


Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-4		0.4	1.0	8:08	NNW
MS-5		1.4	2.5	15:41	NNW
MS-6		0.0	0.0	23:59	N
MS-7		0.1	1.0	7:00	WSW
MS-8		0.1	1.0	14:09	N



Air Monitoring Notes:


MS1 H2S MONITORING RESULTS - 03/09/23

NON-PROPERTY LINE MONITOR




MS2 H2S MONITORING RESULTS - 03/09/23

NON-PROPERTY LINE MONITOR




MS3 H2S MONITORING RESULTS - 03/09/23

NON-PROPERTY LINE MONITOR




MS4 H2S MONITORING RESULTS - 03/09/23

AT OR NEAR PROPERTY LINE




MS5 H2S MONITORING RESULTS - 03/09/23

AT OR NEAR PROPERTY LINE




MS6 H2S MONITORING RESULTS - 03/09/23

AT OR NEAR PROPERTY LINE



MS7 H2S MONITORING RESULTS - 03/09/23

AT OR NEAR PROPERTY LINE



MS8 H2S MONITORING RESULTS - 03/09/23

AT OR NEAR PROPERTY LINE

