


Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT NON-PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey				03/14/23	
					Field Operations	
					Page 1 of 1	Rev. No. 0
					Submitted By:	
				30 Minute Avg H ₂ S Action Level	30 ppb	

Weather Data Range from Full Weather Station		Wind Direction	WNW	Relative Humidity (%)	57.7 - 85.8	Daily Rain (in)	0.05	Landfill Perimeter Monitoring
Temp (°F)	32.5 - 39.0	Wind Speed (MPH)	2.0 - 16.4	Barometer (inHg)	29.57 - 29.76			

*Note: Wind Direction reported in the direction that it is coming from

Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-1		0.7	2.0	17:07	WSW
MS-2		0.0	0.0	0:04	NNW
MS-3		0.7	1.0	2:28	N




Air Monitoring Notes:

Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT AT OR NEAR PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey	03/14/23	
		Field Operations	
		Page 1 of 1	Rev. No. 0
		Submitted By:	
		30 Minute Avg H ₂ S Action Level	30 ppb

Weather Data Range from Full Weather Station		Wind Direction	WNW	Relative Humidity (%)	57.7 - 85.8	Daily Rain (in)	0.05	Landfill Perimeter Monitoring
Temp (°F)	32.5 - 39.0	Wind Speed (MPH)	2.0 - 16.4	Barometer (inHg)	29.57 - 29.76			

*Note: Wind Direction reported in the direction that it is coming from


Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-4		0.5	2.2	22:43	W
MS-5		0.8	1.0	23:59	NW
MS-6		0.0	0.0	0:00	NNW
MS-7		0.0	0.0	0:01	SW
MS-8		0.0	0.2	18:06	W



Air Monitoring Notes:


MS1 H2S MONITORING RESULTS - 03/14/23

NON-PROPERTY LINE MONITOR




MS2 H2S MONITORING RESULTS - 03/14/23

NON-PROPERTY LINE MONITOR




MS3 H2S MONITORING RESULTS - 03/14/23

NON-PROPERTY LINE MONITOR




MS4 H2S MONITORING RESULTS - 03/14/23

AT OR NEAR PROPERTY LINE




MS5 H2S MONITORING RESULTS - 03/14/23

AT OR NEAR PROPERTY LINE




MS6 H2S MONITORING RESULTS - 03/14/23

AT OR NEAR PROPERTY LINE



MS7 H2S MONITORING RESULTS - 03/14/23

AT OR NEAR PROPERTY LINE



MS8 H2S MONITORING RESULTS - 03/14/23

AT OR NEAR PROPERTY LINE

