


Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT NON-PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey				03/18/26	
	Field Operations					
	Page 1 of 1				Rev. No. 0	
	Submitted By:					
				30 Minute Avg H ₂ S Action Level		30 ppb

Weather Data Range from Full Weather Station		Wind Direction	NW	Relative Humidity (%)	23.9 - 59.9	Daily Rain (in)	2.17	Landfill Perimeter Monitoring
Temp (°F)	25.7 - 38.1	Wind Speed (MPH)	0.7 - 14.2	Barometer (inHg)	30.27 - 30.54			

*Note: Wind Direction reported in the direction that it is coming from

Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-1		0.8	2.0	15:17	SSW
MS-2		1.4	2.0	8:27	WNW
MS-3		0.9	2.2	15:27	S




Air Monitoring Notes:

Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT AT OR NEAR PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey			03/18/26 Field Operations	
				Page 1 of 1 Submitted By:	Rev. No. 0
			30 Minute Avg H₂S Action Level	30 ppb	

Weather Data Range from Full Weather Station	Wind Direction	NW	Relative Humidity (%)	23.9 - 59.9	Daily Rain (in)	2.17	Landfill Perimeter Monitoring
Temp (°F)	25.7 - 38.1	Wind Speed (MPH)	0.7 - 14.2	Barometer (inHg)			

*Note: Wind Direction reported in the direction that it is coming from


Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-4		0.4	1.2	15:24	WSW
MS-5		1.2	2.3	22:11	S
MS-6		0.0	0.0	0:04	NNW
MS-7		1.2	2.8	15:05	S
MS-8		1.9	3.0	15:07	S




Air Monitoring Notes:




MS1 H2S MONITORING RESULTS - 03/18/26
NON-PROPERTY LINE MONITOR




MS2 H2S MONITORING RESULTS - 03/18/26
NON-PROPERTY LINE MONITOR




MS3 H2S MONITORING RESULTS - 03/18/26
NON-PROPERTY LINE MONITOR




MS4 H2S MONITORING RESULTS - 03/18/26
AT OR NEAR PROPERTY LINE




M55 H2S MONITORING RESULTS - 03/18/26
AT OR NEAR PROPERTY LINE



MS6 H2S MONITORING RESULTS - 03/18/26
AT OR NEAR PROPERTY LINE



MS7 H2S MONITORING RESULTS - 03/18/26
AT OR NEAR PROPERTY LINE



MS8 H2S MONITORING RESULTS - 03/18/26
AT OR NEAR PROPERTY LINE

