


Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT NON-PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey				09/14/26	
					Field Operations	
					Page 1 of 1	Rev. No. 0
					Submitted By:	
				30 Minute Avg H ₂ S Action Level	30 ppb	

Weather Data Range from Full Weather Station		Wind Direction	N	Relative Humidity (%)	28.3 - 84.5	Daily Rain (in)	0.00	Landfill Perimeter Monitoring
Temp (°F)	60.6 - 75.3	Wind Speed (MPH)	0.3 - 15.4	Barometer (inHg)	29.94 - 30.35			

*Note: Wind Direction reported in the direction that it is coming from

Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-1		0.0	0.3	9:31	W
MS-2		0.4	2.0	14:59	NNW
MS-3		0.0	0.0	0:00	NW




Air Monitoring Notes:

Keegan Landfill Monitoring Project 	DAILY AIR MONITORING REPORT AT OR NEAR PROPERTY LINE Keegan Landfill Monitoring Stations Kearny, New Jersey		09/14/26	
			Field Operations	
			Page 1 of 1	Rev. No. 0
			Submitted By:	
30 Minute Avg H ₂ S Action Level			30 ppb	

Weather Data Range from Full Weather Station		Wind Direction	N	Relative Humidity (%)	28.3 - 84.5	Daily Rain (in)	0.00	Landfill Perimeter Monitoring
Temp (°F)	60.6 - 75.3	Wind Speed (MPH)	0.3 - 15.4	Barometer (inHg)	29.94 - 30.35			

*Note: Wind Direction reported in the direction that it is coming from


Station Location Area	Work	Daily Avg. 30 Min H ₂ S Concentration (ppb)	Max 30 Min H ₂ S Concentration (ppb)	Time of Max 30 Min H ₂ S Reading	Corresponding Wind Direction
MS-4		0.0	0.3	0:27	NE
MS-5		0.0	0.0	0:03	SSE
MS-6		0.0	0.0	0:05	SW
MS-7		0.0	0.2	10:20	NNW
MS-8		0.0	0.0	0:03	S



Air Monitoring Notes:


MS1 H2S MONITORING RESULTS - 09/14/26

NON-PROPERTY LINE MONITOR




MS2 H2S MONITORING RESULTS - 09/14/26

NON-PROPERTY LINE MONITOR




MS3 H2S MONITORING RESULTS - 09/14/26

NON-PROPERTY LINE MONITOR




MS4 H2S MONITORING RESULTS - 09/14/26

AT OR NEAR PROPERTY LINE




MS5 H2S MONITORING RESULTS - 09/14/26

AT OR NEAR PROPERTY LINE




MS6 H2S MONITORING RESULTS - 09/14/26

AT OR NEAR PROPERTY LINE



MS7 H2S MONITORING RESULTS - 09/14/26

AT OR NEAR PROPERTY LINE



MS8 H2S MONITORING RESULTS - 09/14/26

AT OR NEAR PROPERTY LINE

